

List January 2024

| <i>Stock</i> | <i>Part No</i> | <i>Description</i> | <i>Make</i> | <i>NSN</i> | <i>DMC</i> |
|--------------|----------------|---|----------------|------------------|--------------|
| 1 | | 436 Starrett micrometer 2" to 3" | | | |
| 1 | | 550 Unidentified part - wiring plus bolt-on box (transducer? Proxistc | Flexible Lamps | 6220-99-660-9903 | |
| 1 | | 550 Rubbolite white marker light | Flexible Lamps | 6220-99-660-9903 | |
| 1 | | 967 Moore & Wright micrometer 2" to 3" (dated 1943) with indicati | | | |
| 1 | | 967 Moore & Wright micrometer 2" to 3" (dated 1943) without indi | | | |
| 2 | | 31034 12-point bolt | Paccar | ends 983 | |
| 5 | | 040809 Bracket, dovetail (for night vision equipment) | | 5855-99-978-3545 | |
| 1 | | 55716 Screw | | 5305-15-203-3983 | 9CLV (Iveco) |
| 2 | | 57568 Clamp | | 5340-99-826-8120 | |
| 2 | | 57568 cable clamps | | | |
| 7 | | 58614 Pack of 10 Hagglunds bolts - black round head Torx | BAE Haggglunds | 5305-14-542-0397 | |
| 10 | | 79125 Brake pipe clip | | | |
| 10 | | 79127 Brake pipe clip | | | |
| 1 | | 165513 Electricity kit | | | |
| 1 | | 182281 Icer pads for AUDI SQ7 4.0 TDI QUATTRO 4MB FRONT BRAKE PA | | | |
| 1 | | 202552 12V 40A Relay | Ripaults Ripca | 5945-99-127-3124 | |
| 3 | | 217400 (Was NT3359) Series 3 oil seal front axle tube separates oil in di | | | |
| 9 | | 230140 Cork gasket, PTO cover 1948-84 | | | |
| 1 | | 233677 Shim pinion bearing front 0.020" | | | |
| 1 | | 233677 Pack of Shim diff pinion bearing (front) 0.020" SERIES | | | |
| 2 | | 234124 Timing Chain Idler Wheel Bush 2.25 Petrol, 2.0 Diesel and 2.25 I LR | | | |
| 4 | | 236995 Locker for brake shoe retainer 10" brakes | | | |
| 4 | | 241839 Maybe more (SET?) Locker for gearbox foot Series 48-84 Fowal | | | |
| 4 | | 241839 Locker for gearbox foot Series 48-84 Foward Control 2A, 2B | LR | | |
| 2 | | 242139 Front tow ring (for X832) | | | |
| 10 | | 243714 Spring clip, gear lever | | | |
| 2 | | 0245187 Overflow valve | DAF | 2.91012E+12 | |
| 5 | | 246464 Dowel rear crank seal | LR | | |
| 1 | | 247824 Land Rover Gasket Inlet to Exhaust Manifold 2.25 Petrol. (2478: Allmakes | | | |

| | | | | |
|----|---|---------------|------------------|-------------------|
| 10 | 247861 Plug, tapped feed gallery plug, front pipe, 2 & 2.25 litre | | | |
| 10 | 264024 Washer, shock absorber, bottom | | 5310-99-849-9919 | |
| 1 | 265461 Dowel for front spring 11 leaf (all Series with 11 leaf springs) | LR | | |
| 50 | 267451 Spring for timing ratchet 2 litre & 2.25 litre diesel | | 5120-99-817-0546 | 7BD |
| 19 | 267575 Mainshaft 2nd gear thrust washer .135" - 4 & 6 Cylinder Gearbc | | | |
| 10 | 267575 Thrust washer | | | |
| 1 | 271014 Washer for Steering Box Land Rover Series 1956 - 83 Genuine | Land Rover | | |
| 1 | 271014 Washer for steering box 1956-1983 | | | |
| 6 | 272501 Angle adaptor for gearbox foot RH | LR | | |
| 30 | 272804 Accelerator cross-shaft bracket Series IIA & III | | | |
| 2 | 278161 2.25 petrol manifold liner (inlet) inc lightweight | | | |
| 1 | 288374 Control valve (brakes) | | 2530-99-990-8335 | 6MT9 |
| 2 | 304301 Clamp hoodstick | | | |
| 3 | 310599 Pack of 10. Trim clip (obsolete) for P4 | | | |
| 5 | 332146 Tailboard bumper rubber | Hobson | 5340-99-805-4577 | Series 3 (4 per v |
| 1 | 332392 Rear upper tailgate gusset LH Stay plate tailgate | | | |
| 6 | 334121 Bulkhead air vent pins Hinge Pin for Front Vent Lid and Rear No Allmakes | | | |
| 1 | 334898 Tie bar radio accommodation frame Series military 24V (more k | | | |
| 1 | 334898 Tie bar radio accommodation frame Series military 24V (more k | | | |
| 10 | 336351 Pickaxe plate / washer | LR | | |
| 1 | 346426 Blanking plate window catch / lock Series 3 | LR | | |
| 3 | 346849 Bush bonnet hinge | | | |
| 1 | 347452 Stiffener instrument cowl Series III RHD | | | |
| 3 | 347668 Grill clip Series III | | | |
| 2 | 350031 Gasket | Lister Petter | 5330-99-208-9399 | |
| 1 | 390587 Bracket range rover rear seat base for Range Rover Classic | | | |
| 2 | 390587 Bracket Range Rover Rear Seat Base | LR | | |
| 4 | 390637 Retainer LH door seal RR | LR | | |
| 10 | 395143 Staple, body side | Land Rover | | 7RU, 7XD |
| 17 | 0486578 Tee piece | DAF | 4730-99-859-1184 | |
| 18 | 486578 T piece tee (for washer?) | DAF | 4730-99-859-1184 | |
| 10 | 501389 Dowel | | | |
| 5 | 501389 centre bolt 109 rear springs Series II/III | | | |

| | | | | |
|----|---|----------|------------------|--------------------|
| 4 | 504213 Shim | | | |
| 20 | 504213 Shim, shackle 109 1 Ton & 101 FC | G | | |
| 4 | 504213 0.003" shim shackles 109 1 ton and forward control | | | |
| 1 | 512237 Bell housing clutch inspection plate 1948-1984 | | | |
| 5 | 515325 Valve plug in timing chain piston 2.25 litre petrol Series II & III | | | |
| 2 | 515325 Valve plug in timing chain piston, 2.25 litre | | | |
| 10 | 515325 Pack of 5 Valve plug in timing chain piston 2.25 litre petrol (£ pe | | | |
| 1 | 524765 35mm core plug | | | |
| 1 | 527269 Plug (BR1411?) | | | |
| 10 | 528865 Stud transfer box to gearbox, 1964-84 | | | |
| 1 | 531040 Steering relay arm upper | | | |
| 1 | 531040 Secondhand steering relay arm upper | | | |
| 2 | 538134 0.10" Crank thrust washer. All 4 cylinder to 1954, Series 61-84, | | | |
| 60 | 539717 Shim 0.030" | | | |
| 3 | 543803 Fuel tank mounting bolt | LR | | |
| 10 | 544337 Bolt for steering relay retainer | LR | | |
| 8 | 549229 TYC100030 Grease nipple yoke on propshaft | | | |
| 1 | 551508 Ignition switch, petrol | Britpart | 5930-99-809-3098 | Series |
| 1 | 552575 Dust cover and horn contact | | | |
| 10 | 552818 shock absorber bushes | | | |
| 12 | 554602 Rocker pedestal / bracket 2.25 litre petrol - Pedestal for Rocker | | | |
| 2 | 555837 Warning light, red, panel | | | |
| 19 | 556633 Thrust washer, bevel gear gearbox diff, 4 speed V8 | | | |
| 1 | 560967 Plate | | | |
| 1 | 561221 Spring, 4 wheel drive selector below yellow knob, Series (110m | | | |
| 1 | 569006 Petrol cap military 117mm dia o/a x 35mm high | | | Series military, : |
| 1 | 569155 Hose front heater 2.25 litre 1968-71 | | | |
| 2 | 569339 Master cylinder cap | | | |
| 3 | 569714 Servo pipe, inlet manifold to servo, Series 2.25litre petrol 4 cylir | | | |
| 2 | 571066 Thrust washer mainshaft for 2nd & 3rd gear V8 4 speed box LT& | | | |
| 1 | 576138 Clutch release fork Series III, V8 & Td5 | | | |
| 5 | 577272 Bolt | | | |
| 1 | 577665 Brake pipe to master cylinder, Series III 109 | | | |

| | | | | |
|----|---|------------------|------------------|------------------|
| 1 | 577874 Steady strip for fan cowl | LR | | |
| 1 | 02/3500 Amber reflector triangular | perei | | |
| 6 | 589553 Striker shroud assembly top of steering colum Series 3 | LR | | |
| 4 | 591597 Pipe diff lock vacuum | | | |
| 4 | 591597 Vacuum Pipe Manifold to Diff Lock Switch, white Genuine | LR | | |
| 7 | 593863 Felt seal for stub axle (Front) and felt seal for bearing sleeve (Rear) | | | |
| 1 | 595447 101 Master cylinder (no cap) (Lucas Girling part No 64046304) | | | |
| 1 | 598852 Land Rover Series 3 2.25 Diesel Accelerator / Throttle Cable | | | |
| 1 | 599698 Stub axle collar | Series 2 & 3 Lig | | |
| 5 | 608246 Diff drain & fill plugs | Britpart | 4730-99-823-7480 | Series, Defender |
| 2 | 624027 U bolt (front suspension hanger?) | | | |
| 1 | 1000198 Force Protection engine mount / isolator (for Cougar / Ridgeback) | | 5340-01-581-3699 | |
| 1 | 1001557 3/8" Hose fitting (SAE45 flare) | National Aerosol | 5935-01-553-1995 | |
| 5 | 1203038 Reducer (Google Norgren for price?) fuel line pipe reducer (for DAF) | | 4730-99-870-0310 | 7FW |
| 1 | 1203258 Hub oil seal THIS IS RARE - PRICED AT £180.00 on eBay (Stemco Stemco for DAF) | | 5.33099E+12 | 7FW |
| 1 | 1203797 DAF adaptor bush (no photo) | | | |
| 1 | 1203919 Stud coupling | DAF | 4730-99-449-3037 | |
| 1 | 1321580 Oshkosh pressure protection valve | | 4820-01-132-0583 | |
| 1 | 2050510 Seat belt (Oshkosh, 3point centre RR 2050510 (complete?)) | Oshkosh | 1000-93-205-0510 | |
| 2 | 3009191 Force Protection oil cooler mounting block | | 1000-93-300-9191 | |
| 1 | 3371578 Oshkosh Lock cylinder + 2 keys | | 1000-93-337-1578 | |
| 2 | 3389272 Oshkosh ISO STD test connectors | | 1000-93-338-9272 | |
| 1 | 3404704 Delta Power Co (USA) 24V (?solenoid switch) ?Oshkosh | | | 4707 |
| 22 | 3732075 Rubber mounts top of shock absorber (from Box 35 Keyfox) | | | 7FN & 6MT1 |
| 9 | 3901356 Gasket for Turbocharger CUMMINS TURBO DIESEL(6BT) Engine | Cummins | 5330-99-767-9545 | |
| 1 | 3943548 Volvo bracket | | 1000-93-394-3548 | |
| 1 | 4850301 Brake unit (is this a master cylinder without actuator rod??) | JCB | 1000-93-485-0301 | |
| 8 | 7181809 Washer (no photo) | 7BD | 5310-99-802-5135 | |
| 1 | 7996946 Windscreen wiper motor 24V (minor rust) (may fit Defender) | Bedford | 2540-99-833-9982 | |
| 4 | 8841878 Gasket manifold/turbocharger | | 2815-99-763-6033 | 7BD |
| 2 | 9458857 TT AB connector SB14SPC | | 5935-99-01-47122 | |
| 1 | 10003236 USED earth cable / battery link | | | |
| 2 | 10011892 Force Protection Hose, transmission, oil | | 1000-93-001-1892 | |

| | | | | |
|----|---|----------------|--------------------|----------|
| 7 | 10606233 Hose (See box 61 & 36) | | 4.721E+12 | 7FW |
| 1 | 10606233 Rubber hose 57mm i/d, 70mm o/d, 76mm long (See box 36, 6/: DAF | | 4720-99-794-3982 | 7FW |
| 1 | 10901121 Seal | | 5330-99-822-5836 & | 7FW |
| 1 | 29509637 Speed sensor, transducer motional pick-up, output speed sensc Allison | | 6695-01-361-6056 | 7VK |
| 54 | 40371502 Grease nipples, greaser (what size are these?) | | 4730-99-822-7960 | |
| 6 | 64223025 Boot dust & seal (?Supacat) (see Box 603, 30, 6/12B) | | 2.531E+12 | 6MT9 |
| 4 | 64325009 R clip (part number = Lucas - see Box A) | | 5340-99-836-7124 | 46MT9 |
| 1 | 64325009 Lucas R clip | Lucas | 5340-99-836-7124 | 46MT9 |
| 1 | 64677157 Boot seal (see Box 6/12B & 30 & 604) | | 2.531E+12 | 46MT9 |
| 7 | 84760545 Harley Davidson amber lens for MT350 & MT500 (also fits Triun HD | | 6220-99-799-6237 | 7AMG |
| 1 | 84860139 Harley Davidson hand-grip | HD | | |
| 30 | 90512701 UNF bolt transmission brake hub to rear prop, Series except V8 | | | |
| 5 | 90575220 Festoon bulbs | | | |
| 3 | 91089903 Bedford (battery?) bolt (coach bolt m8 x 240mm) | | 5306-99-769-3038 & | |
| 3 | 91103656 Spring assembly (no photo) | | 2510-99-781-3717 | |
| 1 | 91111033 Bedford O ring (large) | | 5331-99-725-7848 | 7BD |
| 4 | 110217294 Sellock Roll pins, roll tension spring, slotted | | 5315-00-844-3663 | |
| 1 | 110223285 Flat washer | | 5310-01-107-3359 | |
| 2 | 241038074 Door seal for Warrior | | 2590-99-773-5443 | 9MVC |
| 10 | 392715400 Gasket exhaust manifold | Cummins | 5330-99-147-3371 | |
| 1 | 504026046 CTS Control Unit | | 2530-15-187-4020 | |
| 1 | 04139430127 O ring for FV101 Scorpion AFV | | 5330-99-943-0127 | |
| 3 | 7581430031 Adjusting washer, shim 40/25.5/0.3 | | 5310-99-896-0838 | 7SDP |
| 40 | 13069063069 Loose ditto | | 5.341E+12 | |
| 1 | 74041000000 Holt Lloyd Pilote double acting pump | | | |
| 2 | (241)AE095RRC 4810RC4810 Knob for Door Top Window Lock Wolf | | 5355-99-974-3749 | 7RU, 7XD |
| 2 | 00782ER & 6346323 & 6346323 ERF / Bedford clutch spring | | 2520-99-874-0770 & | 7BD |
| 2 | 0119936, HT048414, R9166/193 DAF bracket slack adjuster | | 2520-99-382-5532 | 7FW |
| 9 | 012KC0012 & 855579 Seal set | | 5330-99-931-7837 | |
| 12 | 021J8004 GASKET-VALVE / Rocker COVER C3282805 | Cummins | 5330-99-665-6639 | 7MD |
| 10 | 42090 EY, V92942090, 3305190R1 Hose assembly (Iveco 3305190R1) | Iveco / Seddon | 4720-99-834-8205 | |
| 2 | 0352572 & 352572 & Y101 883 09 Hose, mini-measuring (Atlas Terex UK Ltd, Bareningsbilar EKA A | | 6685-99-978-5390 | 7FW |
| 1 | 749/40 & 10197468 & 0410W-001 Adaptor (adapter), oil drain pipe, adaptor fitting lubrication | | 4730-99-154-2856 | LFG2KW |

| | | | | |
|-----|---|----------------|------------------|----------------|
| 1 | 05216100 & HZ05216100 Seal for Harrington Generator (HATZ Diesel Sealing Strip 545 MILFG2KW | | 5.33012E+12 | |
| 142 | 059-0147 Bussmann NATO 15 amp fuse | | 5920-99-059-0147 | |
| 1 | 070011535 & FV546143 Min/max controller Bendix (?A/C ex AFV) USED (u/s?) see photo | | 6110-99-804-4010 | |
| 1 | 1741922EA & 7MD/NIV-72-001132 Penman plug sensor switch | | 1000-93-074-1922 | 7MD |
| 8 | 865648 & AMPB788 & FV2188509 Tilt drain valve 1/2" | Paccar | 2530-99-778-9485 | 7FW |
| 3 | 0876-2-705169-003 Strap 800mm Long - 25mm Wide (Package Control UK) for Ptarmigan | | 5340-99-775-6129 | |
| 30 | 0876-2-705169-003 Strap 800mm Long - 25mm Wide Ptarmigan radio | | | Z88-5340-99-77 |
| 1 | 0876-2-705169-003 Strap 800mm Long - 25mm Wide (Package Control UK) for Ptarmigan | | 5340-99-775-6129 | |
| 9 | 09-00032-00 Door seal for Foden DROPS | | 2510-99-517-8333 | 7FN & 7WTK |
| 1 | 09-00032-00 Door seal for Foden drops (on shelves) | | 2510-99-517-8333 | 7FN |
| 24 | 0953 4521-0 & 0211Z-011 O ring | | 5331-99-537-3131 | 7MD |
| 1 | 10002793-0101 Bracket assembly steering column | General Dynam | 2590-01-607-4119 | |
| 2 | 10012119-0101 Force Protection alternator mounting | | | |
| 3 | 100934300, 84720333 Stop light switch Harley MT350, MT500 | Unknown | 5930-99-733-8135 | 7AMG |
| 1 | 10470AD6-18 & MS20470AD6-18C Price per 100 (not counted) Aluminum alloy 2117 rivets, aircraft | | 5320-00-242-0307 | |
| 1 | 10606233, HT040? DAF rubber hose (ex Box 61) | | 4720-99-794-3982 | 7FN, 7FW |
| 3 | 11-00123-100 Frame Section, Structural (Cross-member? Foden DROPS or T24 | | 2510-99-401-8898 | 7DP? (or T244) |
| 1 | 112/1817 Valve | Caterpillar | | |
| 1 | 11590-528 Roller bearing (lower swivel pin bearing?) | CBF | 3110-99-950-8998 | 7RU |
| 1 | 11A1025C Dayco belt 200Tdi | | | |
| 1 | 1203919, HT025171 Stud coupling DAF | | 4730-99-449-3037 | |
| 1 | 120908 & C-CS0359-175 & 120407 Pre-heat relay | CMCA, Easby El | 5945-99-687-2555 | |
| 15 | 13011-HN0-A02 0.50mm oversize Piston ring set TRX450 Foreman | Honda | | |
| 9 | 13069063069 & 02669234073 Set of 5 red caps dust and moisture seal | | 5.341E+12 | |
| 10 | 1340/0403Z Pack of 5 nuts M12 | JCB | 1000-93-340-0403 | |
| 1 | 1402564 & HT034567 & LB6074/2 DAF LF45 Front Anti Roll Bar Bush - mount bearing bush CHECK | Paccar | 5340-99-701-0983 | 7FW |
| 1 | 14039D & FL19836 & 35NM53846 Air intake cleaner (1/8" BS21 thread) (breather grade D) | Filton Ltd | 4120-99-962-2851 | |
| 4 | 1404689, HT040183 Stud | DAF | 5307-99-409-6815 | |
| 4 | 1404689, HT040183, 53K0243 Metric stud rear axle hub | | 5307-99-409-6815 | 7FW |
| 1 | 15.160.01-5 or 15.160-01-S Kohler rope | | | |
| 18 | 15-160-01 Kohler engine starter rope | | 2990-01-348-5966 | |
| 1 | 1583-1272, CV139482 Terex Benford exhaust pipe 40mm ID, 45mm o/diameter x 425r TB | | 1000-93-583-1272 | |
| 7 | 16973-150 Golight spotlight control Snatch / control panel | | 6220-99-579-8000 | 7NP |

| | | | | |
|----|--|------------------|------------------|------------------------|
| 2 | 16973-150 & Spotlight control panel Golight (Snatch?) more in Box 24 | | 6220-99-579-8000 | 7NP |
| 9 | 1721877-0 1721877-0 Cummins oil pan sump gasket Mowag Duro (see Wo | | 5330-99-212-4266 | |
| 1 | 1721877-0 1721877-0 Cummins oil pan sump gasket Mowag Duro (see Wo | | 5330-99-212-4266 | |
| 10 | 182-504 Pack of 2 elbow pipe to tube 1/4" to 10mm | | | 7MV |
| 1 | 1886379C1 Navistar Husky sump | | 2815-01-577-2568 | 7HSKY |
| 1 | 19068-76 Packing pad | National Aerosol | | |
| 1 | 196 026 02 & 10897094 Fuel gauge assembly | | 6680-99-829-3963 | 7FN |
| 2 | 1R Polybush set of 4 bushes replaces LR part nos 552819 and NRC5 | | | |
| 3 | 20053-1 Onan condenser / capacitor | Onan | 5910-00-583-4517 | |
| 3 | 20071688 20071-688 VOSS hoses (fuel tube) (For Haggglunds BV206??) BAE | | 4710-99-147-6097 | |
| 10 | 2017486C1 & 68PMT-4-6 Copper alloy pipe adaptor 250psi Max operating (Parker equiva | | 4730-01-521-2609 | |
| 10 | 2018-0345 Spring dowel pins | | 5316-99-200-6486 | |
| 1 | 202719 & 202640 Proxistor (more Box 8&29) | FACET INDUSTF | 1730-99-341-7883 | 7MTE |
| 2 | 202719 & 202640 Proxistor (more Box 7&29) | FACET INDUSTF | 1730-99-341-7883 | 7MTE |
| 1 | 202719 & 202640 Proxistor assembly (more Box 7&8) | FACET INDUSTF | 1730-99-341-7883 | 7MTE |
| 1 | !329, 2540013922329, 013922329 Oshkosh door handle inside LH (FTX Logistics) | | 1000-93-202-7480 | |
| 10 | 56781 & 21152215361 & 6320171 Rivet | Haggglunds | 5320-99-364-0492 | |
| 1 | 21315-199, 5199, CV169735D Hinge spacer (no photo) | | | |
| 1 | 218/6776 Cover assembly | Caterpillar | 1000-93-218-6776 | |
| 29 | 241038074 & 5443 Door seal for Warrior AFV | | 2590-99-773-5443 | 9MCV |
| 1 | 247/00366 4mm spacer | JCB | | |
| 1 | 26.59.09 Relay v. shop soiled & rusty 200A 24V (CHECK 26.59.09 & 1145: Kisslingworld.c | | | |
| 1 | 6324-27 & F48-33G3 & G0003001 Strainer, sediment (marked serviceable so not new?) | | 4730-99-822-0930 | |
| 1 | 54407 & 02/100073A & BFF67975 Perkins oil filter | | 2910-99-209-1458 | |
| 1 | 26591-12T00 Nissan rear lens red | Nissan | | |
| 5 | 2663-439-001 Connection block + diode | BAE | NIV-56-000562 | |
| 2 | 267125SP End cover, air dryer | Knorr Bremse | | |
| 2 | 267125SP & 0692368 End cover assembly (AD2) for air dryer | Knorr Bremse | 2530-99-700-6273 | |
| 3 | 27145-10038-2300 Plate label convoy switch SAXON APC. NSN. 9905-99-734-4651. BAE | | 9905-99-734-4651 | |
| 18 | 2716 15700 354 EA Retainer torsion spring | | | 5.361E+12 9MCV Warrior |
| 1 | 281257 & 583642 Valeo clutch pressure & friction plates Defender Discovery 2 Td Valeo | | | |
| 1 | 2950-9637 Allison speed sensor (Supacat MD3560P output speed sensor) | | 6695-01-361-6056 | 7VK |
| 1 | 2950-9637 Allison speed sensor (Supacat MD3560P output speed sensor) | | 6695-01-361-6056 | 7VK |

| | | | | | |
|----|----------------------------------|---|------------------|------------------|-----------|
| 2 | 2SA964169091 | Rear light assembly (no screws) | Hella | | |
| 1 | 308892 & 4002884 | End bolt (for Snatch??) | | 5340-01-548-6326 | |
| 1 | 31-056-54-143 | Obsolete Mann oil bath filter for Mercedes (Unimog??) | | | |
| 10 | 312-0057 & 312-A57 | Onan condenser / capacitor | Onan | 5910-00-519-9134 | |
| 16 | 312-0058 | Onan condenser / capacitor | | 5910-00-451-7598 | |
| 10 | 54475S1 - 31-634-583-01 - 559247 | Locking ring (Washers) (more in Box 36) | | 2910-99-828-5390 | 7FW |
| 1 | 316758A1 | Switch (Case parts 921C, 721C, 621C, 821C) | CNH | 5930-01-502-0035 | |
| 6 | 3305188R1 & 021SJ-004 | Hose (1 in box 21B) | Iveco | 4720-99-840-0597 | |
| 1 | 3305188R1 & 021SJ-004 | Hose IVECO (more Box 6&12B) | | 4720-99-840-0597 | |
| 7 | 331/33869 | Indicator (fork leg position?) | JCB | 3830-99-927-5357 | |
| 1 | 331/33869 | Indicator fork position (position indicator?) | JCB | 3.831E+12 | |
| 1 | 335/03428 | Pipe assembly | JCB | | |
| 10 | 34 0278 03 | Olives (small) or sleeve | | 4730-99-913-5588 | 7FN |
| 1 | 347/20602 & A63796 | Battery strap + | JCB | | |
| 4 | & 23725 & ST46002 & FV1033042 | Small tube, sleeve compression, hose fitting | BAE (also Norgi) | 4730-99-209-9678 | |
| 1 | 3802968 & 3972071 | Thermostat (Cummins 397 2071) 54mm 180°F & Box 6&12C & | Perkins | 6685-01-343-1572 | |
| 9 | 38710-HM7-004 | Honda fan control unit | Honda | | |
| 1 | 395083, FQJ103850 | L/H Anti-burst door lock | Unknown | | 7RU & 7XD |
| 1 | 3S-8447 | Caterpillar V belt (1 set consists of 2 belts) SOLD?? | | | |
| 6 | 402 5270 | Cummins unidentified part (4025270 is a front crankshaft seal f | | | |
| 1 | 406187A1/0 | Hydraulic ram (query last zero may be 10) | | 2590-99-733-2630 | 7FN |
| 20 | 41014196 9160036 Y032 044 02 | Pin, roller, brake shoe Bedford | | 5315-99-830-5137 | 7BD |
| 1 | 41029073 & R8116/69F | Spacer ring (Uni-Power, Power GP PLC) | | 5365-99-761-7569 | 7FN |
| 1 | 41269317 & CV175065A | Hose (brake?) | Iveco | 4710-12-377-9900 | |
| 1 | 421-210-004 | Earth strap Dytecna (no photo) | | | |
| 1 | 421-210-005 | Earth strap Dytecna (no photo) | | | |
| 1 | 4410 328080 | Wabco inductive sensor | | 2530-99-782-3392 | |
| 4 | 45/911000 | Coupling | JCB | | |
| 1 | :000220 & FV2064057 & ACU8710 | Wabco coupling yellow (palm) quick connect | | 4730-12-174-4905 | 7FW |
| 1 | 453/01807 | Pressure plate | JCB | 1000-93-530-1807 | |
| 4 | 4A104 | Tube BAE | | 4730-99-209-9678 | |
| 10 | 4RD003520-07 | Hella 24V relay 10/20A | | 5945-12-301-1144 | |
| 1 | 4S1-G6137-01 | Seal, drive shaft (Big Bear & Grizzly) | Yamaha | 5330-99-400-2272 | |

| | | | | | |
|----|----------------------------------|---|--------------|--------------------|------------|
| 4 | 501-059-0067 | Transducer / sensor (rust on mounting bracket) | Moffett | | |
| 1 | 9504104917 & 16-1007-1002-14 | Switch (504104917 is Iveco Part Number) (COBO, Iveco, BAE) | BAE | 5930-15-203-3876 | |
| 1 | 51-00176-002 | Fitting, bulkhead (Foden DROPS) | | 4.731E+12 | 7FN |
| 1 | 5100589000 & HT029032 | Quick release valve | Paccar | 2530-99-253-5496 | |
| 1 | 510451-1 | Cable & conduit (brake?) | | 2.53099E+12 | 7TR |
| 3 | 510451-1, 560-007-443 | Boughton or Rubery Owen trailer brake cable | Smith&Prince | 2530-99-305-3499 | 7TR |
| 4 | 5300-288 | Red + twin entry battery terminal, 61x59x21mm | Ricardo | 5940-99-481-9629 | 7XD |
| 1 | 5300-418 | Bracket clamp rear (angle bracket) | | 5340-99-471-5184 | |
| 4 | 53165-958-010 | Honda hand-grip Fourtrax, TRX350, TRX450, ATC1855A | Honda | | |
| 2 | 533-8 & 9975663 | AC Delco (533-8) radiator cap Bedford (9975663) Perkins (6527) | | 2540-99-881-3781 | |
| 1 | 539-001 | Load indicator and transducer by Loughborough Projects Ltd (N | | 507-059-0000 | |
| 2 | 5631K300 & NRC7874 | Land Rover brake hose?? 1129 - GBH321 - NRC7874 with (grea | | 4720-99-786-7626 | |
| 2 | 5631K300 & NRC7874 | Land Rover brake hose?? 1129 - GBH321 - NRC7874 without (g | | 4720-99-786-7626 | |
| 1 | 569714 | was NRC6192 Servo to hose manifold pipe | | | |
| 7 | 571066 & BR3394 | (From other box - adjust later) thrust washer (NOT shown to Jar | | | |
| 1 | 571970 & 998238013 | Retainer (Oil shield part number 571970 for the rear output on | | 5330-99-823-8013 | |
| 1 | 79 61-01, 580854701, 580796101 | Non-genuine MANDREL SPINDLE KIT HUSQVARNA CTH184 T CT | | | |
| 1 | .32463 (EO No)& 27-09-07 (date?) | Quick release coupling | | 4730-99-477-5752 | 7SA |
| 2 | & RCR4610 & 5325-343 & 244711 | pinion starter 24V Land Rover 2.25 Petrol Starter Motor (minor | | | |
| 1 | & RCR4610 & 5325-343 & 244711 | CAV pinion starter 24V Land Rover 2.25 Petrol Starter Motor (b | | 2920-99-804-1781 | |
| 10 | 610833 ERR4383 | Defender V8 carb spacer | ? | | |
| 1 | 612/80156 | 3/8" BSP hose x 800mm JCB 3CX | JCB | | |
| 1 | 61-90 & KY1467/13 | Bendix Hand brake parking control valve (not the same as DPM | Bendix | 2520-99-757-9217 | |
| 2 | 62-40-251-2 | Latches, Southco (lift & turn) Supacat?? | Southco | | |
| 2 | 6343151 576204 600858 | Land Rover military MoD rearstop-light lens 7RU | | | 6MT3 |
| 1 | 64223025, VTS5A2/2087 | Boot & seal Meritor brake system LS & LS/1 (see Box 603 or 6/1 | | 2530-99-824-3869 | 6MT9 |
| 98 | 64677157 & TKSYS1/2418 | Boot and seal, brake (see 603, 604 & 30) | Meritor | 2530-99-824-5639 | 46MT9 |
| 2 | 65540S1 & 12270 | reservoir Cap filler opens (actually the screw lid of a can) Filler C | | 2590-99-762-6262 | 7SA |
| 1 | 3937027BE & MGR51 & 68937025 | Brake shoes CW590457 Defender rear 1990 on | | 2530-99-829-8489 & | 6MT9 & 7RU |
| 1 | 6KK342 | Air spring (more somewhere) | | | |
| 1 | 6KK342 | Air bag cab | | 1000-93-034-2393 | |
| 1 | 6KK342 & 1101-0061 | Link Goodyear Super Cushion Air Spring - Part numbers 1101-00 | Goodyear | 1000-93-034-2393 & | |
| 1 | 70 20 810 | CV joint hub spacer 7MV/NIV-72-000931 | | | |

| | | | | |
|-----|---|---------------|-------------------|-----------------|
| 1 | 70-05-525 O ring | | 5.33101E+12 | 7DE |
| 1 | 70-05-533 & 3967195 Cummins thermostat for Supacat opens at 180degF | | 4820-99-133-6891 | |
| 1 | 70-05-533 & 3967195 Cummins thermostat for Supacat opens at 180degF | | 4820-99-133-6891 | |
| 4 | 701/58884 JCB decal (switch escutcheon) worklights actuator switch (No. 7 JCB | | | |
| 1 | 70-20-205 Supacat High Mobility Vehicle CV joint kit, inboard | Supacat | 2520-99-997-1619 | 7MV |
| 1 | 70-20-205 CV joint inboard Supacat HMT | | 2520-99-997-1619 | 7MV |
| 12 | 70-20-810 Spacer wheel hub CV joint for Supacat 4x4 high mobility vehicle | | 5365991479519 and | 7MV |
| 2 | 70-2599 MDG1226 Chubb Fire labels for DE&S | | 9905-99-137-1484 | |
| 2 | 70-75-280 7MV Supacat engine wiring loom / assembly | | 1000-93-707-5280 | |
| 1 | 70-75-280 Engine loom | | 1000-93-707-5280 | |
| 1 | 721/11296 Link lead / electrical connector | JCB | | |
| 10 | 72180/CE Haldex automatic brake adjuster | Haldex | 2530-99-168-8272 | |
| 3 | 72180/CE Haldex automatic brake adjuster | LR | | |
| 3 | 82-0 & AT 29536299 & 021K6-032 Seal assembly oil Automatic Transmission Fluid Pump (Front M | | 5330-99-872-1793 | 7MD |
| 1 | .144, 522M1144, WVA 200271600 Brake pads, Mintex C-Tech. MGB, Jaguar E-Type 71-75,. XJ6 72- | | | |
| 1 | .144, 522M1144, WVA 200271600 Brake pads, Mintex C-Tech. MGB, Jaguar E-Type 71-75,. XJ6 72- | | | |
| 1 | 7786/76 Wheel stud (Ribbed bolt) 7/8" BSF-LH for Dana-Spicer powertra Imperial Engine | | 5306.99.828.7210 | 6MT10 |
| 9 | 7786-76 Ribbed bolt / stud (wheel stud? GKN-Kirkstall-Dana 7786/76?) | | 5306-99-828-7210 | 7BD |
| 53 | 78586 & 078586 Pack of 25 Phillips Screw fixing Series III grille £ per pack | | | |
| 200 | 78586 & 078586 Phillips Screw fixing Series III grille (Approx 8 open packs + loos | | | |
| 7 | 2 & 298125ZA893 & 81254360089 Fuse (mega-link fuse 125A green TO CHECK) MAN 7933100012 | | 5920-99-255-1619 | 7SV |
| 1 | 80-10-1350-OR Lampholder & cap assembly | Paramount Pan | 6210-99-881-5622 | 9ACR 430 Series |
| 10 | 1005187 & 1203064 & 94 4601 01 Pipe adaptor tube to pipe (Norgren??) | | 4730-99-147-1164 | 7FW |
| 1 | 81-12210-0007 Filler cap (MAN HX truck) | MAN | 5342-12-335-0361 | 7SV |
| 1 | 82-47304-2503 MAN pipe elbow / connector | | | 7SV |
| 1 | 82-63730-6045 Mirror, 24V, heated | MAN | 2540-01-550-7874 | 7SV |
| 1 | 55889 & 3293103R1 & 3307724R1 24V Relay | | | 7FW |
| 3 | 8T-1887 Clip | Caterpillar | 1000-93-000-1887 | |
| 4 | 907-602-12 Springfix clevis pin | DAF | 5315-99-827-5130 | |
| 1 | 910 55129 & 91055129 Bedford speedo cable | | 6680-99-837-8915 | 7BD |
| 15 | 9104 2778 Strap | Bedford | 5340-99-747-8540 | 7BD |
| 2 | 914/35401 Spider kit / UJ | JCB | 1000-93-143-5401 | |
| 27 | 921/53500 Spacer kit | JCB | 1000-93-215-2500 | |

| | | | | |
|----|--|---------------|--------------------|----------------|
| 4 | 954475S1 Locking ring (Washers) (more Box 24) | | 2910-99-828-5390 | |
| 1 | 960 (more) Locking pin, Supacat | | 5325-99-373-0761 | |
| 1 | 966B Moore & Wright micrometer 2" to 3" (Box 243) | | | |
| 2 | 966B Moore & Wright micrometer 2" to 3" (Box 249) | | | |
| 1 | 980/11406 Lever RH | JCB | | |
| 2 | 1210, 5315005140210, 005140210 Pin | | 5315-00-514-0210 | |
| 7 | 92 & 3350456R1 & A-1205-J-2428 (MORE BOX 603) AY-oil seal (A1205R2592 Pinion Oil Seal Meritc Meritor | | 5330-99-846-3144 | |
| 4 | A121783 Bracket (ref 1162?) | Manroy Engine | ?.99.027.6777 | |
| 4 | A24Q Grinding (scrubbing) discs for dry grinding metal 180 x 6 x 22mr | | | |
| 2 | A2NN1031 & FV773705 Vehicle identification plate (Serial no. etc) T244 | | 9905-99-824-1770 | 7FW |
| 1 | m 10-3930-675 & tm 10-3930-675 sensor, manifold absolute pressure, emission control, Brough r | Kalmar | 2990-01-479-2322 & | 3990-01-473-39 |
| 1 | A6000075 Bedford adaptor air compressor s/s coupling yellow | | 2530-99-867-8596 | |
| 7 | -0568 & 286 & LLB286 & RTC3635 12V 1.2W bulb (in Box B) these will fit cigar lighter bulbholder a | | 6240-12-171-6626 | 7RU & 7XD |
| 7 | -0568 & 286 & LLB286 & RTC3635 12V 1.2W bulb (in Box B) these will fit cigar lighter bulbholder a | | 6240-12-171-6626 | 7RU & 7XD |
| 1 | AA-2267-365 Penman spring lock cover | | 1000-93-226-7365 | |
| 5 | AA-2323-337 Retainer wheel nut for lightweight trailers | | 2430-99-258-0413 | 7LWT |
| 2 | AA-2508-668 Arm (not sure what for) (Honda arm lower front?) | | 2530-99-171-8985 | |
| 10 | AA-2592-1604 Netting bungee cord (105cm cords, 65 x 50cm net when stretch | | 2540-99-666-8570 | 7MD |
| 5 | AAU1981, ESR3710 Clip (Petrol Defender fuel tank vent pipe) | G | | |
| 1 | AB/02/03/04211 250 bar Pressure gauge - stainless steel 316 & safety glass. Liqui Wika | | 6605-99-500-1453 | 9AS9 |
| 2 | AB/02/03/04211 Pressure gauge | Wika | 6685-99-500-1453 | 9AS9 |
| 1 | ABU7244 Indicator Lens Leyland Constructor / Drops / Roadtrain T45 | | 2540-99-422-989 | 7FW |
| 1 | ABU7244 Indicator Lens Leyland Constructor / Drops / Roadtrain T45 (wit | | | |
| 20 | ABU7482 Cable | DAF | 2590-99-787-1506 | |
| 2 | ACAP797 & KAL5002 Handle, window winder (KAL5002 is T244) | DAF | 2590-99-978-3086 | 7FW |
| 1 | ACU1855 Control rod (gas strut front panel) | DAF | 2.591E+12 | 7FN |
| 2 | ACU1984 & TT6804/00 BAE systems temperature sensor (DAF, Foden) | | 6685-99-793-7901 | |
| 5 | ACU2539 Bush (mount resilient spring) | | 5340-99-794-2734 | 7FN |
| 20 | ACU3801, DTO11876 Pack of 5 - DAF pipe clip (£1 ea) | | 5340-12-160-0827 | |
| 10 | ACU8240Y01 Clip | DAF | 5.32099E+12 | |
| 2 | ADU4946 Clip linkage | DAF | 5.32599E+12 | |
| 1 | ADU6847 Sealing washers | | | |
| 2 | AELB185 Switch, oil pressure | DAF | 6620-99-700-7961 | |

| | | | |
|----|---|------------|---------------------------|
| 1 | AELB646 & MXK350 & 359143 USED VDO C15 speedo (electronic) | VDO | 6680-99-724-2132 & 7FW |
| 1 | AELD230 & 13659 Washer pump | DAF | 2540-99-244-3296 |
| 1 | AEU1986 Shut out of shunt box 24V airportable & military Series 3 | | |
| 1 | AEU2409 Cannot find - check part number (could it be a SERVO PLUG??) | | |
| 1 | AEU2515 Seal, Salisbury diff pinion | Land Rover | 5330-99-784-2678 7RU, 7XD |
| 1 | AEU2537 Defender caliper 110/130 with solid discs up to 1986 front RH (i ? | | 2530-99-797-7059 |
| 1 | AEU4019 Dust Seal for Input Shaft on Manual Steering Boxes.r/Rover and | | |
| 11 | AFP5052 & HT031983 Knob, heater control | | 5.356E+12 7FW |
| 5 | AFU1248 Washer | | |
| 10 | AGU1425 & 928010300 Price per 10 (not counted) ITW Fastex 75 (TFC) Trim/upholstery Infast | | 5325-99-786-8385 7FW |
| 4 | AK608151L Nut hex (more in box 79?) | | |
| 1 | ALR6105 Label body colour | | |
| 1 | ALR6498 Defender front window button guide / clip | | |
| 5 | ALR6871 Bolt, 40mm long | | |
| 1 | 177 & 505730 & 13659 & AELD230 Screenwash pump (13659 for T244) | | 2540-99-244-3296 |
| 2 | AMPB564 Seat base (rusty) | DAF | 2.54012E+12 |
| 5 | AMPB670 Strap, clamp propshaft | DAF | 5340-99-452-8979 |
| 9 | MPB670 & HT037817 & 6.5-70-89 HTO037817 Strap propshaft | | 5.34099E+12 7FW |
| 1 | AMPC181 Oil seal RUSTY | | 5330-12-322-3769 |
| 3 | AMPC181 & 900.9.0831.60 Oil seal (65MM shaft dia & 85mm housing dia) | | 5330-12-322-3769 6MT1 |
| 1 | AMR2341 Relay wiper delay | | |
| 2 | AMR3025 Washer jets | | |
| 1 | AMR6106 Wash wipe switch, Defender from VIN VA104806 on and Wolf 7 BM | | Gen £50 / BM or Luca |
| 1 | AMR6106 G Wash wipe switch, Defender from VIN VA104806 on and Wolf 7 G | | too dear?/ |
| 1 | ANR2381 Bracket, mounting, bumper, rear. Range Rover P38 | | |
| 3 | ANR3679 wheel nut Disco II (some in CLEAR 12) | | |
| 3 | ANR3679 Disco wheel nut (some in CLEAR 3) | | |
| 1 | ANR3738 Mounting body to chassis P38 (obsolete part - last one) | | |
| 2 | ANR4164 A frame bush (s/s LR018259) | LR | 5340-99-924-5416 7XD |
| 2 | ANR4487 Rear axle top link | Gen | Defender (&Disc |
| 1 | ANR5804 Also RYG501550 Radius arm bolt to axle M16 x 100mm Defend LR | | |
| 1 | ANR6461 Radiator Cowling Mounting Fastener Td5 (Deutz fastener??) | | |
| 1 | ANR6703K Mounting rubber | | |

| | | | | | |
|----|--------------------------------|---|---------------|------------------|----------------|
| 1 | ANR6704 | Mounting rubber ACE pipes | | | |
| 1 | ANR6971 | Radius arm bush | Hobson | | Defender |
| 5 | AS64363-514Z | Pip pins (quick release?) (Anixter Industrial) | | 5315-99-837-3126 | |
| 5 | ASC31316 | BAE systems screwed plug (no photo) 3/8" UNF | BAE | 5365-99-942-7984 | 46MT1 |
| 1 | ASU710070 | Bracket for horn mounting | LR | | |
| 4 | ATC25 | Box of 5 Buss 25A ATC blade fuses | Buss | 5920-99-759-5255 | |
| 1 | AUU1405, SBK5908 | Brush Set for Starter Motor 2M 100 Type Petrol Series 3 (AAU1, Allmakes | | | |
| 4 | AWR4782 | Gasket Blower Motor Heater 90/110 | | 5330-99-611-5317 | 7RU & 7XD |
| 1 | AWR5109 | Yellow plastic plug CHECK - cannot find online | | | |
| 1 | AZL043 | Cooper filter (small & tatty cannot sell) for Lister / Petter | | | |
| 2 | B1178454 & FL15928 & NM35003 | Pin, straight | | 5315-99-962-2651 | NI or N1 |
| 2 | BA15S | 12V15W bulbs LLB207 | | | |
| 6 | BA9s | 8Gp002 & 066-241 small 12v bulb | | | |
| 10 | BDC710040 | Small black plastic shims for doors BHC710010 & BDC710040 | | | |
| 1 | BH608321L | Tow bar bracket to chassis 1/2" UNF x 4" | LR | | |
| 1 | BHB710061 | Bottom hinge, multiple applications. Lower rear Series II, IIA, III | | | |
| 7 | BJH3976 | Land Rover Defender 2.25L Petrol & Diesel Lower Coolant Radiator | | | |
| 74 | 0946, RAK9062, 505617, RAK8062 | DAF bushing pipe (RAK9062 or RAK8062???) | | 4730-99-457-5040 | |
| 2 | BR0635 | Small lock washer CHECK - cannot find online | | | |
| 70 | BR100050 | Sellock spring roll pin | G? | | |
| 1 | BS0396 or V8464 | Engine support bracket / brace / beam | | 5120-99-773-1235 | 6MT2 or 7FW |
| 4 | BTC50R | Large 70mm red + battery terminal (stud type terminals) | | | |
| 1 | BTR1599 & MXC3189 | Land Rover Defender Windscreen Heater Vent Demister L/H. | | | |
| 1 | BTR2564 | Hose Assembly Condenser to Evaporator | | | |
| 5 | BTR4419LOY | Trim fastener dark granite | LR | | |
| 1 | BTR6061AAT | Plug front seat inner & outer valence walnut | LR | | |
| 1 | BTR6188 | damaged Air intake grille, 300TDi, Supacat, in wing Defender front | | | |
| 1 | BTR6188 | Genuine air intake grille | | | |
| 1 | BTR6562 | Seat belt assembly RH front | Britpart | 2540-99-320-4788 | Defender 89-20 |
| 1 | BTR9634 | washer spring clip 8mm (obsolete) | | | |
| 5 | BX110091L | Bolt M10 x 45mm Rear Link Bracket | LR | | |
| 2 | BX110095M, FTC940 | Set of 5 bolts for drive member flange special M10 | Hobson | 5306-99-808-7428 | 7RU |
| 30 | C28512 & 994960703 | Pin, lock on lanyard (for DROPS) (also NATO pintle?) | Marshall Land | 5.31599E+12 | 7DP |

| | | | | |
|----|--|------------------|----------------------|----------------|
| 1 | CA90029 & ACU8718 & HE5887 Clutch cover plate FLYWHEEL COVER ASSEMBLY CLUTCH FOR D | | 2520-99-742-4368 | 7FW |
| 1 | CA90029 & ACU8718 & HE5887 Clutch cover plate - RUSTY FLYWHEEL COVER ASSEMBLY CLUTCH | | 2520-99-742-4368 | 7FW |
| 1 | CAL9975 & C604 Nylon pipe | | 4710-99-836-1404 & | 7BD |
| 1 | CBU1716 & 328879000 Drive belt for 7CE Cummins engine | DAF | 3030-99-814-9083 | |
| 1 | CF3509333 Quick-release valve | Seddon Atkinsons | 2530-99-735-8636 | 7SA |
| 4 | , FVS21/2, RR36A, EH-12-0021379 Reflector amber circular 115mm dia | | 9905-99-803-1630, 62 | |
| 1 | CFE500670 Seal, door, lower | Gen | 5330-99-500-5064 | ALR6250 |
| 2 | CFE500670 & LR029309 Weathering strip, door, lower Genuine | LR | 5330-99-500-5064 | 7RU |
| 10 | CRC1250L Brake pipe clip | | | |
| 1 | CS20A-F-ST62 3 Position switch (although actually 6) 240V 6A panel mount | IMO | 1000-93-000-0622 | |
| 1 | CV134643 Union | | 4730-99-502-2772 | |
| 20 | CV14161 Lock washers, key washers | Perkins | 5310-99-729-6544 | 7PK |
| 1 | RR/CV2473 & CV2473 & PCV2473 Perkins oil filter (rusty) | Perkins | 2940-99-796-8199 | 7FN |
| 1 | CV67896 Gasket for rocker cover for 7PK Perkins Diesel Engines | Perkins | 5.33099E+12 | |
| 4 | D726010159 BA9s miniature 24V 4W MCC bulb clear | | 6240-99-918-3660 | 7SDP |
| 2 | DBP3067 DPP3067L ? Probably DBP3067L M12 nut also RYH100590 for s LR | | | |
| 2 | DBP8169L Cable clip plastic 13-17mm, 7mm hole | | | |
| 1 | 108-36T10-06PE 508/1/31003/130 Plug 10-6 Mk 18 AB Connectors | AB Connectors | 5935-99-015-0035 | Z32 |
| 2 | DKB103340 Wiper arms P38 RHD RH side (driver's) | BM | | |
| 15 | 882 5076 & 8825084 & MVA1500 Bow handle | | 5340-99-631-6943 | |
| 1 | DLY000010 Spacer - Ferrule windscreen wiper | G | | 7XD |
| 1 | DOS500030 Tube, wiper rack | Land Rover | | 7RU, 7XD |
| 1 | DPB000270 Defender black military bumper (part number may be Britpart) | | 2540-99-739-7188 | |
| 1 | DPB000270 Black military Defender bumper | | 2540-99-739-7188 | |
| 1 | DPM85AX Handbrake valve | Knorr Bremse | 2530-99-372-8822 | Iveco |
| 5 | DPSM6210012 Seal - trailer hub | M-TEC | 5.331E+12 | 7TR |
| 1 | DQN100120 Bracket, mounting, bumper | | | |
| 1 | DQN100120 Bracket, mounting, rear bumper Freelander 1996-2006 Genuine LR | | | |
| 2 | EE41442 FTG ST 6NPT Bushing | | 4730-00-202-6491 | 7WTK Oshkosh ' |
| 1 | EN8557356 Seddon Atkinson (Iveco??) hose (more Boxes 21B & 601) | | 4720-99-758-9367 | |
| 12 | EN8557356 Hose (more In Boxes 21B & 63) | Iveco | 4.721E+12 | |
| 1 | EN8557356 Hose NO LABEL - assumed EN8557356 | Iveco | 4.721E+12 | |
| 1 | EN8557356 & 0114A-004 Seddon Atkinson / IVECO hose (not cable) (more in Boxes 63 & | | 4720-99-758-9367 | |

| | | | | |
|----|---|------------|------------------|----------------|
| 5 | EN9361037 Pegaso Seal | Pegaso | 2590-99-251-9965 | |
| 2 | ends 3676? Jerry can holder (fire extinguisher holder?) | | | |
| 40 | ERC3896 Baffle plate for air filter (lots) | | 2.54099E+12 | 7RU |
| 1 | ERC5875 Heat shield manifold to starter V8 | | | |
| 7 | ERC7295 Wading plug | LR | 5365-99-732-7008 | 7RU |
| 1 | ERC7295 Wading plug | OEM | 5365-99-732-7008 | Defender 200 & |
| 5 | ERC8155 Stud, Series, stepped sump, diesel | | | |
| 5 | ERC8155 Stud Stepped Sump (Optional) Series 3 Diesel, Genuine | LR | | |
| 1 | ERC9056 Valve rocker inlet (RH inlet valve rocker arm) | | | |
| 1 | ERR1070 Genuine Plate Mounting Spark Plug Lead Retention on V8 Wate | | | |
| 10 | ERR1209 Spacer between rocker shaft | | | |
| 1 | ERR2081 Td5 temperature sensor / sender | | | |
| 1 | ERR2337 Rubber mount 300Tdi air filter (& others?) | | | |
| 2 | ERR2409 Gasket valve rocker arm cover 300TDi | G | | |
| 1 | ERR2789 300Tdi rad fan - a bit rusty . Genuine | LR | | |
| 1 | ERR2798 300Tdi fan | G | | |
| 1 | ERR2799 300Tdi fan USED | | | |
| 1 | ERR3291 Used but good 300Tdi thermostat | | | |
| 1 | ERR3734 Water pump pulley | LR | 3020-99-832=3114 | 7XD |
| 1 | ERR4085 24V Relay timer for glow plugs | Land Rover | 2815-99-911-5804 | 7XD |
| 31 | ERR5173 Land Rover spark plug lead (FFR) see Box 37B also | LR | 2920-99-061-2145 | 7RU & 7XD |
| 4 | ERR559 Tappet adjusting screw 200TDi | LR | | |
| 1 | ERR5926 Plate camshaft retainer | | | |
| 1 | ERR6005 Alternator belt (fan belt) for 300TDi FFR military (24V) | ? | 3030-99-126-2985 | 7XD, 7RU |
| 1 | ERR6951 Tensioner Pulley (probably u/s) | | | |
| 1 | ERR7094 Britpart early TD5 rocker cover gasket | | | |
| 1 | ERR7094 Gasket for rocker cover (early Td5) | | | |
| 1 | ERR7143 Oil seal, timing cover 300TDi | | | |
| 1 | ERR7296 Pulley 300Tdi auxiliary / air-con belt tensioner | Hobson | 3020-99-664-0916 | 300Tdi engines |
| 1 | ERR7296 & ERR2797 Pulley, auxiliary drive | LR | 3020-99-664-0916 | 7XD |
| 1 | ERR7297 Seal, air-con belt tensioner cover 300Tdi | Land Rover | | 7RU, 7XD |
| 5 | ERR7386 Pulley tensioner 300 Tdi | Land Rover | 2920-99-462-8092 | |
| 2 | ES120K8024BR Faulty speedometers speedos (CHECK part number) | | | |

| | | | | |
|----|---|---------|------------------------|-----------|
| 2 | ESR2084 gearbox oil cooler hose (also 1 in Box 11) | ? | | 7XD |
| 5 | ESR2579 Oil cooler pipe clamp | | | 7XD |
| 1 | ESR2747 Air filter | | 2940-99-894-8658 | |
| 1 | ESR2747 was ESR2623 Air filter, Defender 300TDi, Wolf 7XD | BR | | |
| 1 | ESR2747 was ESR2623 Air filter, Defender 300TDi, Wolf 7XD | BM | | |
| 1 | ESR3172 Mount, resilient (exhaust hanger) | Unknown | 5340-99-940-5918 | Defender? |
| 1 | ESR4103 Cooper air filter AG1204 (mice damage to seal but OK) | Coopers | Freelander 1 | |
| 1 | ETC4422 Cover plate, diesel (not Tdi) 2.5 litre diesel and turbo diesel | LR | | |
| 2 | ETC5815 & 13A0725C Dayco belt 200Tdi power steering | | | |
| 1 | ETC7207 Pipe Oil Feed to Turbo - 2.5 Diesel Turbo up to engine No 19J29 | | | |
| 1 | ETC8001 300 Tdi valve inserts | | | |
| 85 | ETC8001 Exhaust valve seat liner 200 Tdi | BM | 2530-99-811-8177 | |
| 1 | ETC8560 Idler, timing belt Genuine For 200Tdi & 300Tdi | LR | 3020-99-605-8205 | 7RU |
| 1 | EV251615L10100 TRW power steering pump (CHECK part number - last 5 digits) [TRW | | | |
| 1 | EYC00010 Clip, trim retention | | | |
| 1 | EZM000110 Radiator Cowling Mounting Fastener Clip | | | |
| 1 | F13428 Seat belt Oshkosh USA 1MM1 Indiana Mills IMM1 | | 1000-93-341-8180, 25LP | |
| 1 | F8852 Rad Haz curtain LH (probably for 7XD - similar part numbers on | | 2.541E+12 | |
| 1 | FB108181L M8 x 90mm flanged bolt | | | |
| 1 | FBU4514 Retainer LEYLAND DAF T244 Side Board Clip / Retainer | Paccar | 2510-99-031-7008 | |
| 5 | FBU4514 & B16306 HT033743 DAF T244 side board clip / retainer | | 2.51099E+12 | |
| 1 | FBU4515 Reflector, RH | DAF | | |
| 6 | FBU4516 Reflector, LH | DAF | | |
| 5 | FBU4516 HGV marker board | | 9905-99-617-3167 | 7FW |
| 4 | FBU4643 DAF printed circuit board PCB (no photo) also Box8CLEAR | | 5998-99-662-7342 | 7FW |
| 1 | FBU5239 DAF Valve pneumatic tyre (long metal extended) | | 2640-99-984-7189 | |
| 7 | FBU8617 DAF Lens red (Rubbolite 1698 or 7347) ST027373 | | 6220-99-168-9644 | |
| 1 | FBU9135 Mirror (Leyland) (probably not T244 - see Parts Cat 2-16-12) | DAF | 2540-99-362-7064 | |
| 1 | FC108137 Flanged bolt M6 x 65mm | LR | | |
| 1 | FC108247 Water pump bolt 300Tdi | | | |
| 4 | FC112177P Used bolts (ex X832 shocks?) (D2 wheel bearing mounting bolts | | | |
| 2 | FH964910002 Slide sight assembly (gun part?) | | 1005-99-227-3122 | C1 |
| 7 | FL17006 Collar shaft (query part number - does not relate to web = NSN: Long & Marsha | | 3040-99-962-9875 | |

| | | | | |
|----|---|------------|------------------|-----------------|
| 8 | FL18550 Spring helical compression | | 5360-99-964-8021 | N2 |
| 1 | FL2309SA Sear assembly (gun part not exceeding 30mm) (Warrior part?) | | 1005-99-963-3216 | |
| 1 | FL2309SA Shear assembly (gun part?) | | 1005-99-963-3216 | |
| 1 | FL909/004 Socket end LH thread (Track-Rod End, for FODEN applications,) | | 2.53099E+12 | 7FW |
| 2 | FQB000050 Door striker LH (probably wrongly labelled as FQB000070) Was BM | | | |
| 1 | FQB000050 Door striker LH (probably wrongly labelled as FQB000070) Was G | | | |
| 3 | FQB000050 Door striker LH (note labelled as FQB000070 RH) | Gen | | Military Defend |
| 2 | FRC1032 Needle bearing layshaft, LT85 reverse idler gear, Defender 90/1 | | | |
| 6 | FRC2349 Asbestos! Gasket swivel to axle case | | | |
| 1 | FRC2894 Swivel pin bottom | | | |
| 10 | FRC3327 Clutch release clip | G | | 7RU |
| 1 | FRC3416 Clutch clip (small plastic) | | | |
| 1 | FRC3416 Clutch bearing fork staple (see box 75 LOTS) | | | |
| 45 | FRC3416 (LOTS - 1 sack) plastic staples for clutch (see box 79) | | | |
| 2 | FRC3650 1.975mm shim layshaft LT95 V8 4 speed Series III Defender RRC | | | |
| 2 | FRC5926 Wheel stud (pack of 5) 16mm x 40mm long | | | 7RU |
| 9 | FRC5926 ? Studs | | | |
| 3 | FRC6246 Body Oil Pump in Extension Case LT77 Box 90/110 Discovery an Bearnach | | | |
| 1 | FRC6375 Breather | | | |
| 4 | FRC6783 Front half-shaft spacer shim 0.60mm | Land Rover | | 7RU & 7XD |
| 10 | FRC6786 Front half-shaft spacer shim 1.05mm | Land Rover | 5365-99-788-8039 | 7RU & 7XD |
| 9 | FRC6787 Front half-shaft spacer shim 1.20mm | Land Rover | 5365-99-788-8044 | 7RU & 7XD |
| 9 | FRC6788 Front half-shaft spacer shim 1.35mm | Land Rover | 5365-99-788-8044 | 7RU & 7XD |
| 1 | FRC6800 Lever, down link, Auto transmission valve lever 3 speed to 1986 | | | |
| 3 | FRC7007 or 219995 Cork washer, transfer gear change plate | | | |
| 2 | FRC7686 Housing transmission (diff linkage)Land Rover Transfer Box Sel | | | |
| 1 | FRC8075 Clevis, diff lock selector | Land Rover | | 7RU, 7XD |
| 1 | FRC8154 Mud deflector / shield for diff | Hobson | 2520-99-729-3009 | |
| 2 | FRC8700 Wheel bearing lock nut | | | |
| 2 | FRC9374 Used flange for snatch propshaft (look good!) | | | |
| 4 | FRC9762 Snatch props (weight approx 9kg) | | 2520-99-591-2892 | |
| 1 | FRV2293662 Camera bracket | BAE | | |
| 10 | FS110301 Triangular bottom link suspension bushes to chassis frame. M1(G | | | |

| | | | | |
|---|--|-----------------|------------------|------------------|
| 9 | FS110301L M10 x 30mm bolt suspension lower plate | | | |
| 1 | FS112251L Screw, torx, engine / gearbox mounting. Discovery II | | | |
| 5 | FS504087S Screw | LR | | |
| 1 | FTC1740 1 x Stub Axle Rear 110 Disc Brake 94-98 (OEM) FTC1740G £45. | | | |
| 3 | FTC3401 Seal, swivel housing outer (chrome ball) Defender 1985 on all, [Corteco | | | |
| 1 | FTC4296 Shim countershaft bearing plate 1.477/1.452mm | | | |
| 1 | FTC4889 Mounting bracket (X832 brake lines) | | | |
| 1 | FTC5151 Lock stop bolt. Discovery II | | | |
| 2 | FTC942 Hub assembly Defender from VIN LA930435, Discovery 1 from \ BM | | | |
| 2 | FV0058609000PD Pack of 10 helical spring | BAE | 5360-99-867-4033 | 9ACR 430 Series |
| 4 | FV0201105100RE Pin (eye bolt) | BAE | 5306.99.734.9639 | 9MCV |
| 4 | FV022370340000 Pin assembly (for latch??) | | 5315-99-934-5326 | |
| 1 | FV2011103 Washer LV9/MCV washer bearing soft (for Warrior) | | 5310-99-780-9084 | 9MCV |
| 4 | FV2015501 & FV0201550100RF Pin | Alvis | 5315-99-799-2529 | 9MCV |
| 1 | FV2029758 & FV02?2975900PD Pin, striker (stud) | | 5340-99-798-8120 | 9MCV |
| 2 | FV2065430 Pipe clip (rusty) | BAE | 5340-99-833-1128 | 9MCV |
| 3 | FV2067166 Knob | GKN | 5340-99-621-7176 | 9MCV |
| 2 | FV2140259 Locking pin, trailer | Universal Engin | 2540-99-588-0717 | 7TR & 7LWT |
| 1 | FV2246173 Flat washer | | 5310-99-165-4099 | |
| 3 | FV2256846 & 0531A-0042 Spacer, sleeve | BAE? | 5365-99-933-4541 | |
| 1 | 3075 & 93-229-3075 & 090FP-010 Clamp Assembly LH toggle | BAE | 2590-99-226-0319 | |
| 1 | FV300200 Steel bar, Socket Wrench Handle, 16" x 5/8" dia | | 5120.99.802.6933 | |
| 2 | FV508748 & B92884 Mounting hook | | 2540-99-806-2143 | W21 |
| 5 | FV524847 Handle catch bolt | | 2510-99-865-7021 | 9ACR - 430 Serie |
| 1 | FV563630/1N 2m cable 2 way marked TOW VEH one end & TRLR JUNC other (| | 2590-99-809-1787 | 6MT4 |
| 4 | FV594608 Adaptor respirator (another one loose somewhere) | | 2540-99-804-3324 | 9AHY |
| 1 | 26785 (or FV826785 or FV626788) Vickers hydraulic pump. Model PVB-205-1BGB2. Part No 77685 | | | |
| 2 | FV627996 Cap for interstart socket | | | |
| 6 | FV642212 & AS28246 Fairlead roller (part numbers for qinetiq & BAE Systems NSN 38 | | 2590-99-830-7296 | 9CVT (9CVRT) |
| 1 | FV758406 9CVT Gun barrel clamp | 9CVT | 2590-99-824-3518 | |
| 1 | FV760732 & 7399 USED Lucas red lens for Defender | Lucas | | 7RU |
| 1 | FV760733 & 6341 USED Lucas REAR indicator lens for Defender | Lucas | | |
| 1 | FV760734 & 6377 USED Lucas FRONT indicator lens for Defender | Lucas | | |

| | | | | |
|----|---|-----------------|------------------|----------------|
| 1 | 51946 & G/06/6X19/F/1 & BS3530 Reynolds Boughton recovery cable serial RBS-001-081 | | 4010-99-214-1248 | |
| 12 | FV908721 Warrior 9MCV cable and connectors FV908721 issue 4 and FV908721 | | | 9MCV |
| 3 | FV908721 Warrior 9MCV cable and connectors FV908721 issue 4 and FV908721 | | | 9MCV |
| 2 | FV908721 Cable assembly, Warrior | CLS Systems | 6150-99-841-9798 | 9MCV |
| 4 | FV951049-2 CONNECTING LINK,RIG | | 3040-99-826-8722 | 9AHY |
| 1 | FYC100520 Freelander linkage clip front door latch | LR | | |
| 1 | GDB2131 TRW Brake pads AUDI SQ7 4.0 TDI QUATTRO 4MB REAR BRAKE | | | |
| 2 | GS110501 Land Rover LT77 R380 Grubscrew 5th Speed Stop for 90/110 4 (| | 5305-99-789-8136 | |
| 2 | H00190000 Cleat | | 5340-99-804-1730 | |
| 3 | 160644 & 234451 & 160644GEXD Wiper arm (TRICO 160644) | DAF | 2540-99-304-1544 | |
| 5 | HAH7855 & HT038385 HTO38385 Fastener Oddie fastener (bonnet catch) | | 2.541E+12 | |
| 2 | HAH9114 Wash/wipe arm | | 2540-99-198-2438 | 7FW |
| 3 | HKO04080 Stay bracket step | DAF | | |
| 1 | HLX64640 Osram lamp 24V 150W (ONAN A1/216HLX & HLX64642) | | 6240-99-452-6021 | |
| 5 | HSP677 Connector, test point 1/8" NSPTF | Marshalls Speci | NIV-90-001243 | PPRF |
| 10 | HT004373, FBU4818 DAF bolt & chain / pin | | 5340-99-075-6248 | |
| 21 | T015625 & J0260SDE & HT009812 Snap pin ring pin clip 6mm dia x 45mm pin | | 2540-99-766-8845 | |
| 18 | T015625 & J0260SDE & HT009812 Snap pin ring pin clip 6mm dia x 45mm pin | | 2540-99-766-8845 | 7TR |
| 1 | HT016607, MXH1189, 505617 DAF T244 panel headlamp support | | 2510-99-708-8446 | 7FW |
| 1 | HTE841-2G C/B socket assembly (minilock coupling spare - Eaton Aerospace FR-Hitemp Ltd | | 4730-99-796-9554 | |
| 1 | HTE841-2H C/B nipple assembly (minilock coupling spare - Eaton Aerospace FR-Hitemp Ltd | | N/A | |
| 1 | HTO39709, 100 599 03 Washer bottle bracket assembly | DAF | 5340-99-535-3098 | |
| 1 | ICW500010 Brake shoes transmission Defender from vin XA175163, Range I Delphi | | | |
| 1 | in box 14 or Dining Room? "Spanset" | | | |
| 20 | IV-223019 Interrupter solder lug toggle switch | | 5130145075936* | |
| 2 | JKB000080 RH heater footwell outlet Genuine | | | 7RU |
| 17 | JLS/CS4 Adaptor straight pipe TSW11-04 (James Lister & Sons) | | 4730-99-788-3836 | |
| 1 | JLS/CS4 Straight adaptor James Lister & Sons | | | |
| 1 | JP2219 Sealing ring (aircraft refuelling?) | | 5330-99-207-7136 | W7 |
| 1 | JQI100060 Adaptor tube (Wolf ambulance?) | | | |
| 2 | JQI100060 & 031JF-011 Adaptor tube (there is confusion over the LR part number - it al Hobson | | 4130-99-300-9430 | 7XD (ambulance |
| 1 | JSC314938 Clamping bar for Johnston sweeper (are there more somewhere) | | | |
| 2 | KAL4891 Bracket | | 2.541E+12 | |

| | | | | |
|----|---|----------------|------------------|-----------------|
| 1 | KDH1974 Seat belt 90-90-0739 & F09014 (Supacat 22?09) Foden DROPS | | 2540-99-255-5727 | 7DP |
| 1 | KDK1366 & RDK1746 Spring shackle (more Box 29 & red) | | 4.03099E+12 | 505617 |
| 1 | KIT8012 & F640 & 004617Y Red palm coupling KIT8012 004617Y spare type (also in Box 6& | | 4730-99-303-4047 | |
| 3 | KIT8012 & F640 & 004617Y Red palm coupling spare type (also in Box 8 Clear) | | 4730-99-303-4047 | |
| 1 | KNK500030 NATO pintle hitch front reinforcing plate | G | 2590-99-453-0975 | |
| 5 | L105089B & 143789325 Mounting (bush? Isolating?) rubber (French) | | 5340-14-378-9325 | |
| 10 | LJQ100630 Seal, timing belt cover | | | Freelander 96-2 |
| 4 | LJQ100630 Seal - timing belt cover | | | |
| 1 | LKG100470 Td5 exhaust manifold gasket | | | |
| 2 | LKJ000010 Td5 inlet manifold gasket | | | |
| 2 | LLH500190 LLH500190 Hose - Cyclone Air Cleaner - 300Tdi engine | | 4720-99-342-1028 | 7XD |
| 1 | LMG/1/07003/220 Weald Electronics free socket (aluminium) 6 pin | Weald Electron | 5935-99-013-0953 | |
| 10 | LNO3009L & LN030091 M10 Greaser, grease nipple - right-angled | Paccar | 4730-99-786-6675 | 7FW |
| 4 | LR016715 B post Captive plates for Rear Door Hinges for 110 Defender 19 | | | |
| 1 | LR077708 Land Rover Defender 90/110/130 Right hand O/S Door Hinge U | | | |
| 1 | LR2420010A Wolf XD hard top models, redundant spare wheel mounting hol | | 2540-99-149-9435 | 7XD |
| 1 | LS0100000 V8 sump 5/16" bolt | | | |
| 1 | LU/54571237 Amber screw-in lens 110mm dia boxed | Lucas | 6220-99-803-3989 | LV6/MT3 |
| 8 | LU/54571237 Amber screw-in lens 110mm dia (damaged by damp/rusted) | Lucas | 6220-99-803-3989 | LV6/MT3 |
| 6 | LU/54593393 Lucas lens clear for number plate lamp | | 6220-99-104-2710 | |
| 1 | LVBW1251 Motaquip FRONT WHEEL BEARING KIT PAIR FOR TOYOTA AVEN: | | | |
| 1 | LYG101440 Inlet manifold bolt V8 3/8" UNC x 1.375" | | | |
| 1 | LYP0000501 Screw | Hobson | | |
| 1 | LYP000050L Bolt M8 torx | | | |
| 5 | MAK9048 Bolt 12 point M12 45 MM (gearbox to transfer box prop-shaft L DAF | | 5306-99-957-6265 | 7FW |
| 3 | MDK1330 & 8511012WR70 DAF seal | | 5330-99-910-6827 | |
| 1 | MHK100620 MAF sensor (suspect? Used?) | | | |
| 1 | MHK100620 Sensor Td5 air filter box (used) | | | |
| 1 | MHK100620 Sensor Td5 air filter box (used) | | | |
| 1 | MHK100820 Td5 AAP sensor (air filter box) for YJ02 not X832 (4 pin type_ | | | |
| 1 | MHK100820 TD5 MAP Air Box Intake Sensor | | | |
| 1 | MIL-DTL-117H Elbow | | | |
| 1 | MOA 304A251 Resistor | | 5905-99-451-7593 | |

| | | | | | |
|----|-------------------------------|---|---------------|----------------------|------------------|
| 4 | 1R11064 & 7E9605148 & 8169700 | Locking washer (buffer nut) | | 1015-99-960-5148 | |
| 2 | | MRC4473 Bolt, bonnet mounted spare wheel | LR | | |
| 1 | | MRC4522 Military Defender Models Inc Wolf Connector Cables / Leads St G | | 2540-99-835-9260 | 7XD, 7RU, Serie: |
| 3 | | MRC8388 Land Rover Defender seat box lid clasp | | | |
| 2 | | MRC9669 Defender demister nozzle | | | |
| 2 | MT22 1079 | Ring Externally Threaded | Spartan Motor | 5365-01-529-2366 | 7MF (Mastiff??) |
| 4 | MT22/1177 | National Aerospace spring brake shoe / Marmon-Herrington axl NA | | | |
| 1 | | MTC5084 Mirror head | | | |
| 1 | | MTC5084 Used mirror head (faulty bracket) | | | |
| 2 | | MTC5084 Genuine Defender mirror head 1987-2006 | | | |
| 1 | | MTC6382 Demister tube | Gen | 4729-99-721-4421 | Defender |
| 2 | | MTC6506 Non-genuine Defender 5 barrel lock & 2 key set | | | |
| 1 | | MTC8473 Waist seal Land Rover Defender Front Door Window Waist Out | | | |
| 1 | | MUC1679 Vacuum tank / reservoir 3.5 V8 Defender air con Discovery RRC | | | |
| 2 | | MUC1889 Door Check Rod L.H. 90-110. up to 1988 Rod Type | | | |
| 51 | | MUC1889 Door stay / check early Defender Left Hand to VIN AA303555 (s | | | |
| 3 | | MWC9605 Screw - top of upper tailgate section. Suitable for: Range Rover | | | |
| 20 | | MXC7421 Snapsac clip interior trim rear. Discovery with speakers. | | | |
| 1 | | MXC7652 Door handle Defender | | | |
| 1 | | MXK1253 Lever, manual control | DAF | 5.341E+12 | |
| 1 | MXK1253 & 211932/001 | Control lever (hydraulic) DAF (211932/001 for T244) | DAF | 2520-99-895-9710 | |
| 1 | | MXK2017 Step (removed - packaging left in box) Leyland DAF DROPS?? | | | |
| 1 | | MXK2017 Step (labelled DAF but not T244?) wrapper in BOX29 | | 2510-99-338-7580 | |
| 1 | | MXK2278 Mudguard for Foden drops rear vertical section RUSTY!! | DAF | 2.511E+12 | 7DP |
| 1 | MXK3267 & HT039358(?) | Cable mod battery link | | 2920-99-796-7347 | |
| 5 | | MXK3532 DAF control rod sub-assembly | | 5342-99-980-8788 | |
| 1 | PK09248 & PK09248 & 1000840/4 | Foden Recovery & DROPS wiper motor | | 2540-99-250-1435 | 7FN |
| 1 | | MZH1784 Steering column switch (CHECK if this has 2 keys - if not, part nu Paccar | | 5930-99-938-2079 | 7FW |
| 1 | MZH9117 & 6GM570LLT & 661 | Battery isolation switch | Carwood | 5930-99-107-5488 | 7FW |
| 1 | | MZH9238 Rear light cluster (not for T244) | Lex | 6220-99-702-0233, 62 | 7FW |
| 1 | | MZH9238 Mirror for DAF T244 - No rear light cluster for T244 (?7FW) For | Lex | 6220-99-702-0233 | 7FW |
| 1 | | MZH9238 Rear light cluster for T244 (?7FW) | Lex | 6220-99-702-0233, 62 | 7FW |
| 2 | | MZK1736 Jaw swivel (gearbox linkage) | | 2.52099E+12 | 7FW |

| | | | |
|----|---|-----------|-------------------------|
| 1 | MZK2365, HT041829 DAF stud pillar (no photo) | | 5340-99-860-4980 |
| 7 | MZK2563 Rod (not T244) | | 5.34099E+12 |
| 2 | MZK2707 Spacer | | 5.366E+12 |
| 3 | MZK3514 DAF Fireshield (5K003260) | | 2990-99-623-7853 7FW |
| 1 | MZK4471 & 06637900 Push Button Emergency Power Cut Off | | 4820-99-180-7642 & 7FN |
| 4 | MZK4566 & HT034723 Grommet | | 5.32599E+12 7FW |
| 4 | MZK9055 Plate (more Box 29) seal retainer ring front hub | DAF | 5330-99-349-5308 7FW |
| 8 | N90187101 Ring for VW (O ring??) | VW LT | 5.331E+12 7SDP |
| 10 | NA6625Y Grease nipple 1/4" UNF | | 4730-99-943-9374 |
| 13 | JAH5467 & 22057602 & BBU4162 Spindle nut, wiper | DAF | 5310992580413 & 53 6MT1 |
| 1 | NAK7196 & HT032883 Adaptor straight | | 4730-99-235-4050 7DP |
| 1 | NAK9381 & HT027585 Clevis pin (or rod end?) | Paccar | 5.341E+12 7FW |
| 5 | NAS1351416 Socket Head Cap Screw Fastener Length: 0-63/64", Thread: 1/4" | | 5305-00-477-2714 |
| 1 | NC85499 Multi-core cable assembly (similar to Box 35) New Chapel Electri | | 1000-93-229-3438 |
| 1 | ' & FV2293438 & AP50018923ISS1 Cable assembly (similar to Box 29) New Chapel Electronics (part New Chapel Ele | | 1000-93-229-3438 |
| 34 | NDH1844 & 289 & NDK4884 BA9s miniature 24V 50mA 2W MCC bulb clear | | 6240-99-770-8033 7FW |
| 1 | NDK7764 & HT028537 Deflector | | 2.521E+12 7FW |
| 2 | NIV-74-001276 Pinzgauer Hinge (Vector) | Pinzgauer | 1000-93-200-6031 7SDP |
| 10 | NIV-74-001945 Washer, armour mounting | | 1000-93-530-0743 |
| 1 | NL21B/6192 42LT Lister Petter element (fuel) | | 2.94099E+12 |
| 2 | M119NM34597 & ROFN13708-35 Bush Drg No FL18502 | BAE? | 5310-99-964-5770 |
| 1 | NOT ON Khaki Draper USED core drill 117 x 150mm (SDS drill?) | | |
| 2 | now at TC Snatch spotlight switch | | |
| 2 | NPP101011 Quick release coupling (hydraulic ISO A?? £5 plus VAT & postage) | | 4.73099E+12 |
| 1 | NRC1803 Twin exhaust saddle clamp RRC | LR | |
| 3 | NRC1970 Rad cap and chain for 101FC | LR | 2930-99-828-0890 |
| 1 | NRC1970 Rad cap and chain (new but looks old) for 101FC | LR | 2930-99-828-0890 |
| 2 | NRC1970 Rad cap (no chain) for 101FC | LR | 2930-99-828-0890 |
| 1 | NRC3115 Bottom Radiator Hose 4 Cylinder 1968-84 Series 3 | | |
| 1 | NRC3115 Series III bottom radiator hose 4 cylinder 1968-84 | | |
| 1 | NRC4675 Fuel pipe | | |
| 4 | NRC5593 Shock absorber bushes X832 | | |
| 1 | NRC5824 Non Air Con, hose to cooler (oil?), V8 Defender 1987-2006 | | |

| | | | | |
|-----|--|---------------|------------------|-----------------|
| 1 | NRC5824 Oil cooler pipe 90/110 V8 or water hose | | | |
| 15 | NRC6799 Bulkhead grommet (for hand throttle?) | G | 5325-99-741-2059 | 7RU |
| 2 | NRC7303 Or NRC7503 diesel fuel pipe | | | |
| 1 | NRC7874 Brake hose | | | |
| 1 | NRC8609 Mounting bracket RH Defender radiator | | | |
| 1 | NRC9455 Defender 90 rear brake hose (jump hose?) | | | |
| 20 | NRC9770 Tdi fuel pipe union nut | | 4730-99-793-3134 | 7RU & 7XD |
| 10 | NRC9770 Fuel pipe union nut, RR, Discovery, Defender | | | |
| 1 | NSC100790 crank sensor Td5 | | | |
| 140 | NTC1176 Single brake pipe clip Defender & Disco 1 (packs of 5, 28*5 =140) | | | |
| 5 | NTC1176 Clip, brake pipe | Hobson | 5340-99-244-7878 | |
| 1 | NTC1775 Steering damper bush, Defender 90/110, Discovery, RRC | | | |
| 1 | NTC4329 Top hose | | | |
| 1 | NTC4923 Bracket - cannot identify need PHOTO | | | |
| 7 | NTC6781 Bush, mount, resilient (wide for front radius arm) | | 5340-99-994-0045 | 7RU |
| 5 | NTC8202, RYG501480 Pin - Anti-roll bar bolt | G | 5306-99-535-6877 | 7RU |
| 1 | NTC9360 Cable, throttle 300Tdi | | 2910-99-020-7751 | |
| 2 | NV94AA Bracket (Navistar?) | | | |
| 1 | NY110047L M10 nyloc nut | | | |
| 4 | OD20362 Perkins injector Bosch 0432191789 | | 2.91099E+12 | 7FW? |
| 79 | 595, OE525951, 989-959, 983-754 Pack of 10 thermostat gaskets | | 5330-99-842-6818 | 7RR |
| 10 | 595, OE525951, 989-959, 983-754 Ditto but single gasket | | 5330-99-842-6818 | 7RR |
| 2 | OS92417A Eye-piece Thales | | 1240-99-965-9306 | V6 Fire Control |
| 1 | OYC110070912 Armstrong shock absorber | Armstrong | | |
| 3 | P18-1046 Very large air filters (Bedford TM, (DROPS?) & others) | | 2590-99-833-4687 | |
| 34 | P616-01608 & MPSCBA/0017 Copper Washer 1/2" OD - 5/16" ID for Lister Diesel Engines | Lister Petter | | |
| 1 | P772 or 6/250 or PX0772 Bulgin connector | | | |
| 1 | pack opened filter BL/D5975 DCD drier / dessicator | | | |
| 1 | PAK1664 & 1402564 & LB6074/2 Silent block Anti-roll bar, mount bearing bush | | 5340-99-701-0983 | 7FW |
| 1 | PCH000220K Freelander 2.5 V6 radiator bottom coolant water hose | | | |
| 4 | PCH000220K Genuine FREELANDER 2.5 V6 Radiator Bottom Coolant Hose | | | |
| 1 | 922, 7030599, 045920, 23388028 Carbon metallic brake pads, Performance Friction Corporation, | | | |
| 1 | PHOTO Metal plate, angled, 1 hole, black | | | 7874 |

| | | | | |
|----|--|-------------|------------------|-----------------|
| 2 | PKO9226 Relay | DAF | 5945-99-835-4540 | |
| 1 | PMK100130 Valve boost control - Turbo Waste-Gate Control Valve Td5 | | | |
| 1 | PRC2505 Oil / water thermal switch, 2.25 litre petrol Series III, Defender 1 | | | |
| 1 | PRC2911 Switch diff lock | | | |
| 5 | PRC3131 Mounting bracket for coil | LR | 5340-99-781-6842 | 7RU |
| 2 | PRC3222 USED military 12 pin tow sockets with leads / wires / cables IN C | | | 7RU |
| 1 | PRC3615 7XD washer pump 24V | | 2540.99.517.3104 | 7XD |
| 1 | PRC4277 Wiper arm (hook type) (PRC8559??) | LR | | |
| 1 | PRC4297 Brake light switch | Hobson | 5930-99-797-8645 | |
| 1 | PRC5567 Speedo cable upper, Land Rover 90 & 110 - 4 cylinder to 1986 | | | |
| 1 | PRC6239 USED cover for military 12 pin tow sockets ??SOLD | | | 7RU |
| 1 | PRC9871 Speedo cable Disco I 89-98 LHD V8 | | | |
| 1 | PS10133 INTAKE MANIFOLD MAP PRESSURE SENSOR Td5 | | | |
| 3 | PYC102560L P clip rad expansion tank hose clip | LR | | |
| 1 | QEU101060 USED track rod guard Defender | | | |
| 7 | R3050ML1012 Box of 10 O rings (these are probably 16mm / 18mm) | Freudenberg | 5331-99-923-7739 | |
| 3 | RAK1433 Elbow brass | Paccar | 4730-99-367-1596 | 7FW |
| 10 | RAK1436 Elbow (brass) (more elsewhere) | DAF Paccar | 4730-99-832-0027 | |
| 1 | 436 & 72-00109-004 & 95 4331 12 Elbow brass (more Box 29) | DAF Paccar | 4730-99-832-0027 | 7FW |
| 4 | RAK1441 & 95433130 Elbow, brass, screw tube to push-fit | | 4730-99-046-3098 | 7FW |
| 1 | 3 & 7632472309 & 179-402-0171 ZF steering pump reservoir | ZF | 2530-12-342-7434 | |
| 1 | RAK3826 & HT046669 HTO46669 DAF T244 gear lever gaiter | | 2520-99-500-0144 | 7FW |
| 1 | RD-5-10236-OP & 72R3135 Red Dot Diffuser 72R3135 louvre (3-1/2 in. Diffuser for R-2000 ; Red Dot | | 2540-01-559-0356 | |
| 3 | RDK1746 & KDK1366 DAF Scammell spring shackle KDK1366 RDK1746 ex-MoD NOS (i DAF | | 4030-99-251-3273 | |
| 1 | RDK1746 & KDK1366 DAF Scammell spring shackle KDK1366 RDK1746 ex-MoD NOS (i DAF | | 4030-99-251-3273 | |
| 1 | RGD100682 Link anti-roll YJ02 rear (one fitted this is other side) | | | |
| 2 | RKB101200 Disco air spring (clips missing??) | | | |
| 6 | RNF100090L Shock absorber bushes X832 | | | |
| 1 | RRC3508 Genuine Defender galvanised military bumper | | 2540-99-739-7188 | |
| 1 | RRC3508 Galvanised military Defender bumper | | 2540-99-739-7188 | |
| 1 | RRC4879 Window catch LH | Gen | 2540-99-885-0581 | Military Defend |
| 1 | RRC4966 Sticker battery vent | | 9905-99-660-6531 | 7RU |
| 2 | RRC6681 Pin for Defender military bumper | | | |

| | | | | |
|---|--|------------|------------------|-----------|
| 2 | RRC6682 Spring for RRC6681 | | | |
| 1 | RRC8342 Battery clamp 410mm long (no projections) | Ricardo | | |
| 1 | RRC8413 & RRC8740 Pick axe head carrier & mount | Land Rover | 5340-99-663-4897 | 7XD |
| 6 | RRC8600 24V relays 70A - FFR charging circuit | Land Rover | 5945-99-867-8147 | 7XD |
| 1 | RRC8681 & 51301920 Earth strap FFR Genuine | Land Rover | 6150-99-591-3294 | 7XD |
| 2 | RRC8687 Battery clamp 410mm long (with projections) | Ricardo | 6160-99-865-1185 | |
| 1 | RRC8692 USED jump start socket inter-vehicle (ex MoD) | | | |
| 1 | RRC8742 Bolt, pickaxe head | LR | | |
| 1 | RRC8819 Rear lamp, 21W stop 24V bulb | Gen | 6220-99-605-8263 | Defender |
| 5 | C8819 & RRC8528 & RL35024VHD Stop light Genuine (was RRC8528) 12V/24V (has 24V single filar LR | | 6220-99-605-8263 | 7RU |
| 1 | RRJ100120 Cover for locking wheel nut Disco II | | | |
| 2 | RTC1844 & FV760733 & 6341 Rear indicator lens plastic fish-eye military | Lucas 6341 | 6220-99-823-9797 | 7RU & 7XD |
| 1 | RTC3612 Rotor arm Lucas distributor Series 4 cylinder 54-74 | BM | | |
| 3 | RTC5869 Ball joints RH thread more in FatBall2 & Keyfox | | | |
| 1 | RTC5869 Ball joint, RH thread more in FatBall2 | Delphi | 2530-99-738-0279 | Defender |
| 1 | RTC5869 Ball joint, RH thread | Britpart | 2530-99-738-0279 | Defender |
| 1 | RTC5870 Ball joint, LH thread | Delphi | | Defender |
| 1 | RTC5952 Speedo pinion | | | |
| 1 | RTC6158 FFR battery venting kit | | | |
| 2 | RVL100010 P38 air compressor mount | Allmakes | | |
| 2 | RYF500260 Seal, (actually radius arm washer) | Land Rover | | 7RU, 7XD |
| 2 | RYF500270 Seal, (actually radius arm washer) | Land Rover | | 7RU, 7XD |
| 1 | S1970 Suspension stop(?) | | | |
| 1 | S3549 Bosch air filter for YJ02YUU | | | |
| 1 | Screwed plug | | 5.36512E+12 | |
| 1 | SDB000470 Delphi Rear brake disc for Discovery 2 | | | |
| 8 | SE910441 Screw | | | |
| 1 | sell with next? Resistor | | 5905-99-451-7594 | |
| 5 | SF106201L Screw 6mm x 20mm countersunk | | | |
| 1 | SFB300 & 30632 LUCAS MODEL 155SA HAZARD WARNING SWITCH (?Part nos?) 1 | | | |
| 1 | SHU100340 Brake pipe bracket | | | |
| 1 | SIQG63ES Bearing | SKF | 3120-99-255-1868 | 6MT7 |
| 3 | SK616 ABB electrical contact block (micro-switch) | ABB | 1000-93-012-2547 | |

| | | | | |
|-----|--|------------|----------------------|-----------|
| 5 | SRB601 Lucas relay solenoid (brown) 24V 40A (ref 33RA) | Lucas | 2920-99-201-8279 | |
| 2 | SRB601 Lucas relay solenoid (blue) 24V 40A (ref 33RA) | Lucas | 2920-99-201-8279 | |
| 63 | 4 0413-943-0127 26DK7846 O ring Shamban Aerospace (more in box 6 & 12/B) | | 5331-99-943-0127 | |
| 7 | 3-0127, 26DK7846, 100-334-0062 O ring (more box 21B) equivalent to: Massey Ferguson 7092366 Shaman | | 5331-99-943-0127 & 1 | |
| 4 | ST020587, SE106304 Pack of 5 - DAF screw (bolt) (no photo) (£0.50 ea) | | 5305-99-832-8208 | |
| 19 | ST024560, FBU4566, ST011302 DAF knob rotary | | 5305-12-147-1828 | |
| 110 | ST041700, CBU2044, 505617 DAF plug | | 5365-99-535-6345 | |
| 5 | ST042184, MZK3389 DAF pulley tensioner alternator FFR only pre-Euro 1 T244 | | 3020-99-875-7133 | |
| 2 | ST044441 & BBU5132 Pressure cap | DAF | 2930-99-836-3249 | 7FW |
| 4 | ST045306, MXK2115 DAF bracket | | 5340-99-811-9575 | |
| 37 | ST047509, RDH2340, 505617 Label DAF | | 2520-99-765-5158 | 7FW |
| 2 | ST20105 Plug, engine | Perkins | 5365-99-528-6922 | |
| 12 | STC1121 & ERC9088 ERC9088 Inlet valve V8 | LR | 2805-99-829-9571 | 7RU & 7XD |
| 2 | STC1121 & ERC9088 Inlet valve V8 (Britpart) | | 2805-99-829-9571 | 7RU & 7XD |
| 1 | STC1123 Repair kit clutch master cylinder RRC1970-74 | | | |
| 1 | STC1203 Bulb 10W | | | |
| 1 | STC1209 Headlamp | | | |
| 1 | STC1525, ICW500010, ICW100030 Brake shoes transmission Defender from vin XA175163, Range I | Lockheed | 2530-99-517-2879 | 7RU & 7XD |
| 1 | STC2767 Mounting rubber air suspension box | LR | | |
| 1 | STC2818 Repair kit, slave cylinder Tdi, Td5 | BR | | 7RU, 7XD |
| 1 | STC3072 Spacer | G | 5365-99-250-0821 | 7XDW |
| 2 | 5L0315 & RNB104410 & ANR3539 Wolf shock absorber front | Monroe | 2510-99-987-8757 | 7RU |
| 22 | STC3452 (maybe 25 total) 25mm white trunking tee (cover) (STC2459?) | | 5975-99-983-9790 | 7XD |
| 2 | STC4005 Rope, elastic for PVC hood assembly | | 4020-99-951-8403 | 7RU |
| 4 | STC4034 Wiring connector push-on | | | |
| 1 | STC439 USED Defender horn/headlamp dip/indicator switch | | | |
| 2 | STC4418 Shroud, map reading light cover, Wolf | Land Rover | | 7RU, 7XD |
| 4 | STC4785LCS Roll cage padding ?OEM Cushioning Pad - Cover Seat | | 2.592E+12 | |
| 1 | STC4848 Heater control Genuine | LR | 5340-99-720-8152 | |
| 5 | SX0793 Switch Z32 | Onan | 5930-99-521-3720 | |
| 1 | TOF100010 Td5 hub spacer | | | |
| 7 | TOF100010 Hub bearing spacer ring (yellow code) 15.4mm | Land Rover | 5365-99-262-7089 | 7RU & 7XD |
| 4 | TOF100020 Td5 hub spacer | | | |

| | | | | |
|-----|--|----------------|------------------|------------|
| 4 | TOF100020 Hub bearing spacer ring (red code) 15.3mm | Gen? | 5365-99-270-5427 | Defender |
| 5 | TOF100040 Td5 hub spacer | | | |
| 5 | TOF100040 Hub bearing spacer ring (green code) 15.1mm | Land Rover | 5365-99-223-9687 | 7RU & 7XD |
| 1 | TOF100060 Td5 hub spacer | | | |
| 6 | TP312 & TP-312 Luminescent torch cap for Atex torch | Wolf | 6230-99-751-5158 | |
| 17 | TTC20126 HGV height indicators by Truck & Trailer Components | | | |
| 1 | U5147096 Terex-Demag window | | 9340-99-666-9712 | |
| 1 | U5147096 Terex-Demag window | | 9340-99-666-9712 | |
| 1 | U5147096 Terex-Demag window | | 9340-99-666-9712 | |
| 42 | UNE 312-0027 & 312-A27 Onan condenser / capacitor (5mFd 200V DC) | Onan | 5910-00-429-2601 | |
| 2 | VBSBC64 New but rusty shackles 25CWT | | | |
| 1 | VR2Q99 - SPX Steering wheel puller extractor (1 more CLEAR7) | Kent Moore SP. | | 7BD |
| 1 | VR2Q99 - SPX Steering wheel puller extractor (1 more in Box A) | Kent Moore SP. | | 7BD |
| 1 | VR-2Q99 SPX Kent-Moore puller (NOT Landy steering wheel?) | | 5120-99-817-0546 | 7BD |
| 5 | VR-2Q99 SPX VR2099? Kent-Moore puller steering wheel extractor | | 5120-99-817-0546 | 7BD |
| 1 | XCH50020 Rubber | | | |
| 4 | XFF100070 Reflector Defender | | | |
| 5 | XPB101290 was AMR6105 Indicator, horn and dip main beam switch TD5 models from VIN | | | |
| 1 | XXU9509 USED?? Hose (labelled gauge) 6312/40 & 0171 & 36-00-6566 (?) | | | |
| 1 | Y00451PMA Handle, door pull, inner | Gen | | Defender |
| 1 | PJH118 & 64066041 & 05759307 Lucas Girling slave cylinder | | 2520-99-773-4578 | 7FN & 6MT9 |
| 100 | 8922116 & SP27008 & N183673-7 Dust caps, red, protective (thread 3/4" - 16 ??) | | 5340-99-923-4073 | |
| 5 | Yc155484bd Genuine Ford TRANSIT Yc155484bd Rear Anti Roll Bar Bush | | | |
| 2 | YJC100970 Defender military battery trays | | | |
| 1 | YJC100970 Defender battery tray FFR (perfect condition) | | | |
| 2 | Z7FD8DA Pneumatic (air) tank control valve | ZF | 2530-12-334-6205 | |
| 1 | seal kit | | 5330-99-931-7837 | |
| 1 | Reynolds Boughton trailer leg | | | |
| 1 | air-con(?) air filter (DETAILS??) | | | |
| 1 | Nissan Qashqai door lock (in back of cupboard in its own box) | | | |
| 1 | Foden stub axle / hub RUSTY! | | | |
| 2 | AFV calipers | | | |
| 1 | Heavy recovery eye | | | |

| | | | |
|----------|---------------------------|--|----------------------|
| 1 | | LPG regulator ex my 101 | |
| 2 | | 1200 x 20 Kingstone inner tubes | |
| 3 | MTC6266 CUB102680 MWC4718 | 4mm Front / outer window glass with finger hole NOS ex-MOD | |
| 2 | LR02746 | Very heavy recovery bridle pulley block SWL 19.5T (ex-AFV?) W | |
| 30 | 7PK2092 | Timing belts (in a black sack) DAYCO - OE-7x2092 & 7PK2092 - L | |
| to count | LJQ10063 | Seals (in a black sack) Packs of 10 | |
| 2 | | PTOs (tractor?) | |
| 2 | | Lightweight air portable front springs USED | |
| | 0876-2-705169-003 | Strap 800mm Long - 25mm Wide (Package Control UK) Ptarmig | 5340-99-775-6129 |
| 2 | | ENV axles and diffs 109 One Ton (and others??) | |
| 1 | | M14 wheel stud for Ifor Williams LM, GX, DP, TA510 (cost £3 or | |
| 12 | AZA344 | Air filter by Cooper | |
| 4 | | Molle pouch pouches | |
| 1 | FTC3306 | Caliper Bracket Mounting rear Defender 1987 - 2006. Genuine | |
| 2 | | Molle belt | |
| | A4407090 & 1203982 | Hiab Multilift Control Box | 3950-99-445-4690 7DP |
| 3 | | Briticent grippers (from CLEAR14) | |
| 1 | | 12 Volt oil transfer pump gearbox EP90 | |
| 1 | | Army overalls coveralls flame resistant size 166/96 USED | |
| | FRC9374 | Snatch prop flange | |
| 1 | | Switch 2 pole ON/ON changeover pull & toggle | |
| 4 | | J bolts | |
| 1 | | Small wiper arm (not Defender - series?) | |
| 1 | | Fuel? Hose (1 x short straight & 1 x longer smaller dia) | |
| 1 | | Door clip | |
| 1 | | Caliper seals | |
| 1 | | Hazard light switch & brake switch (USED) | |
| 1 | | Radius arm bolts (old, u/s?) | |
| 1 | | Bump stop | |
| 1 | | Snorkel clip | |
| 1 | | Front wheel hub ABS sensor (ex YJ02 working when removed) | |
| 1 | | Optical technoprobe | |
| 1 | | MF135 manual | |

| | | | |
|----------|----------|--|------------------|
| Lots | | Air con / heater hose black 1.5" / 40mm ID approx | |
| 1 | | Briticent gripper | |
| | | Pipe threaders | |
| 1 | | Ceramic H4 headlamp adaptor | |
| 5 | | Supacat shelf extensions | |
| 1 | | Mirror spares RHS Disco 2 | |
| 5 | AFP1536 | Early Sherpa circular headlamp bezel trim surround | |
| 100 | FRC3146 | clutch pin plastic | |
| 1 | | LH mirror glass Disco 2 | |
| | | Foden battery cover (2?) see opposite T244?? | |
| 1 | | Proxistor screwdriver, etc | |
| 1 | | Clip for pintle | |
| | | Sprinter manual on eBay | |
| | | Discovery 2 II windscreen washer jet LR048709 (Range Rover Sp | |
| 1 | | standard flange (or HD?) | |
| | | Box brass necked bolts | |
| | | Signet socket set (details on other sheets) | |
| 2 | | wire safety straps (connects clip) for pintle | |
| 1 | | Big washer (for engine/gearbox) on eBay?? | |
| | | 220V 9W LED (4 I think) | |
| 1 | | Cambelt (one of many) | |
| | | M5 neoprene flat washers | |
| To count | FRC3416 | Clutch fork staples | |
| | | Rivets | |
| 1 | | Mirror, Cicek, mount 62x56mm, 5 dia bolt/screw, ccs 38 and 23 | |
| | | Sanyo recorder | |
| 4 | | Clips for military snorkel | |
| | | J bolts | |
| | | Hub box spanner | |
| 2 | | Large jubilee clips for military snorkel | |
| 1 | LR030568 | Defender Td5 throttle | |
| 5 | | (NOT genuine Briticent) Gripper inspection lamp clamp/handle B | 4930-99-208-4095 |
| 1 | | Inter-vehicle jump-start socket OLD PATTERN (with backplate) | |

| | | | | |
|----|--------------------|---|------------------|--------|
| 1 | | HGV height indicator | | |
| 1 | | Breathing apparatus dehumidifier dessicant OPENED | | |
| 1 | | JSP Navigator key | | |
| 1 | | Spacer block 95 x 40 x 25mm with 17mm dia & 2 x 12mm dia holes | | |
| 1 | | Mitsubishi brake pads ADC44241 FDB803 PAD668 GDB1023 Part | | |
| 1 | | Mirror DAF/Paccar cracked 2 wires (not 4 as last) | | |
| 1 | | Wagner 5731 sealed beam headlamp 6" sealed beam | 6220-99-783-7503 | 7SPC |
| 2 | | USED Throttle pedals Disco 2 | | |
| 5 | | 32 x 27 x 3mm neoprene(?) washer | | |
| 1 | | RANGE ROVER L322 SEAT BELT PRE TENSIONER AND BUCKLE NE | | |
| 1 | SF17802 & 1R032718 | Sterilisation / sterilant tank (not in packing) (maker TMP?) | 4610-99-605-7749 | |
| 1 | | Briticent Gripper inspection lamp clamp/handle & aircraft refue B | 4930-99-208-4095 | |
| 1 | | Heavy duty towing / recovery eye ex AFV? | | |
| 3 | | Rifle mounts ex-DAF 30x110x70 o/a bolt heads | | |
| 1 | | Interstart leads about 4.5m long (leads: FV324284/5 & 844284, | | |
| 5 | | M20 x 120 Grade 8.8 bolts | | |
| 5 | | Pip pins | | |
| 1 | | Snorkel hose | 1000-93-011-0010 | |
| 1 | | Another Snorkel? hose | | |
| 1 | | Gasket sealing ring | 5330-99-207-7136 | |
| 4 | | Washer locking buffer nut | 1015-99-960-5148 | |
| 4 | | Elbow brass | 4730-99-046-3098 | |
| 1 | | Fluid filter (TO IDENTIFY) | 4730-99-322-3320 | |
| 1 | | Fuel line (TO IDENTIFY) | 1000-93-074-4593 | Penman |
| 1 | | Knob | 1000-00-600-8809 | |
| 19 | | Refill plug | 5340-99-498-9250 | |
| 1 | | Large bracket labelled Hood Support | | |
| 1 | | Banjo (cam?) coupling water? | | |
| 2 | | Defender wiper arm & blade (PRC8559??) | | |
| 25 | | Gearbox thrust washers (not as previous) | | |
| 25 | | (not counted) Helicoil M4 x 1.1/2D Thread insert A2 | 5325-99-624-4995 | |
| 50 | | Price per 10 (not counted) M3x10 spring pin, spring tension pin, | | |
| 1 | | USED Defender mirror, arm & hinge (glass broken) | | |

| | | | | |
|--------------|---|--------|------------------|------|
| veral, vario | Door seals various for what? | | | |
| 11 | Ring Core Ferrite Bead Clamp Choke Coil EMI RFI Noise Filter Cli | | | |
| 1 | Penman Cab lockdown switch | Penman | 1000-93-310-0150 | |
| 52 | "Spansets" | | | |
| 400 | (not counted) Sellock roll pins, ring tension, slotted 3/16" x 1 1/ Anixter Fastene | | | |
| 7 | Swivel pin shims ?817 or ?578170 or 744 | | | |
| 1 | Rocker too heavily preserved to identify (old Landy / Champ?) | | | |
| 1 | Set of brake shoes difficult to identify - 4x10.0 DB 757-250683 2 | | | |
| 1 | Set of brake shoes difficult to identify (No refs) | | | |
| 2 | Set of brake shoes difficult to identify - 104796 or 704796?? | | | |
| 15 | HGV height indicators (plus one in Box 7CLEAR & 2 in BOX24 car | | | |
| 3 | Battery terminal cover red + | | | |
| 21 | Type A elbows ?air line | | | |
| 30 | Type B straight connector | | | |
| MISSING | Ignition switch | | | |
| 24 | Type C elbow | | | |
| 42 | 7.5A blade fuse | | | |
| 1 | Tecalemit pressure gauge 0-11 bar 41mm dia | | | |
| 5 | Sankey (Universal Engineering) link | | 6685-99-795-6401 | 7LWT |
| 1 | USED GM indicator switch | | | |
| 1 | Bracket RH DAMAGED | | 2510-99-277-5705 | |
| 2 | HGV height indicators (plus one in Box 7CLEAR & others in WSW | | | |
| 1 | Nuts & bolts | LR | | |
| 1 | Another white box in workshop with nuts & bolts | LR | | |
| 2 | Pack of 5 pins (tiny) dated 13/3/1979 | | 5315-99-135-2588 | |
| 1 | Washer | | 5310-99-138-4896 | |
| 5 | Ring (washer, O ring) | DAF | 5330-99-978-3250 | 7FN |
| 1 | Set of brackets marked BSB2076.1 and BSB2075.1 and "back of | | | |
| 19 | Ring retaining (no photo) | DAF | 5325-99-301-8006 | |
| 10 | Tubeless valves (no cap) (494??) | | | |
| 25 | Norgren brass plugs | | | |
| 1 | Wheel nut wrench (Bedford?) | | | |
| 1 | Hollow bar (like a short track rod) | | | |

| | | | | |
|-----|---------|---|--|--------------------------|
| 4 | | ?Battery hold-down bars clamps (Bedford?) | | |
| 20 | | Black plastic-coated Terry clips | | |
| 1 | | Littlefuse 125LT 32V | | |
| 20 | | O ring | | 5331-99-823-0902 |
| 2 | | Rubber tube for Defender snorkel | | |
| 20 | | washers | | |
| 5 | | Machine bolts M12x120 grade 8.8 | | |
| 1 | | Two-way terminal kit brass screw | | |
| 1 | | Snorkel hose | | |
| 1 | | Pressure gauge 0-250 bar | | 6685-99-500-1453 |
| 50 | | Schrader valve caps | | |
| 1 | | Spring clip trailer socket, Sankey | | 7LWT-5340-99-874-2: 7LWT |
| 1 | | USED DIN rail, 7 block terminals | | |
| 17 | | O rings | | 5.332E+12 46MT1 |
| 1 | | LR Hose no part number | | |
| 2 | | Old speedos | | |
| 1 | | Extractor fan kit (is this now in its own box??) | | |
| 1 | | Dipstick tube | | |
| 1 | | bolt | | 5305-00-72-5317 DRD |
| 2 | | USED rubber pads | | |
| 1 | | Length of air con / heater hose black 1.5" / 40mm ID approx | | |
| 130 | | 120.5 DET PAT (ducting clips) stainless | | ??ends 236 |
| 2 | | Rubbolite clear lens model 86 | | |
| | MTC6506 | Genuine Defender 5 barrel lock & 2 key set | | |
| 1 | | Battery tester by Performance Chemicals Ltd | | 6.331E+12 |
| 28 | | (count 28 approx) Schrader valve inner | | |
| 1 | | Dunlop 35 952 x 96 42 A1 Hose | | |
| 1 | | Track rod end (marked 4D) | | |
| 20 | | 20A blade fuses | | |
| 1 | | Connector - Weald LMG/1/07003/220 | | 5.93599E+12 |
| 2 | | Box of 50 M6 x 44 shoulder bolt by Anixter | | 5306-99-767-3548 |
| 2 | | Box of 100 steel countersunk machine (screw/ bolt?) zinc passiv | | 5305-99-135-0292 |
| 1 | | Box of 10 1.25" square section spring washer BZP | | 5310-99-724-5081 |

| | | | |
|------|-----------|--|------------------|
| 234 | | M3 flat washer (zinc plated?) some rusted | 5310-99-122-3030 |
| 1 | T0062 | Pagid brake pads - 1 with wear sensor | |
| LOTS | | Jubilee clips and spring hose clips 10mm | |
| | TVC100010 | UJ for Defender Disco 1 by GKN | |
| 10 | | Ball bearings | 3110-99-950-0573 |
| 10 | | Small brass bolts (about M8 x 20mm) | |
| 5 | | Bent tyre extension hose 220mm | |
| 30 | | Nut, steel to BS3692 8mm x 1.25mm | 5310-99-135-0758 |
| 1 | | Hydraulic hose | |
| 1 | | Discovery 2 indicator lens (rough) (RH I think) | |
| 1 | | Discovery 1 indicator lens (new?) | |
| 1 | | Hose Td5 intercooler? (top or bottom?) rubber | |
| 2 | | de-icer aerosol | |
| 1 | | Amber/clear (blue!!) flashing light set | |
| 2 | | webbing straps (mine) | |
| 1 | | Bungee strap | |
| 1 | | Yellow hose PA12 nylon to DIN73378 12mm OD x 1.5m long coiled with screw fittings each end | |